

ss ubi road 1, singapore 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL. NORA.KHAI@PREMIUMAUTO.COM.SG/CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

ACCIDENT REPAIRS

WORKSHOP CONTACT NO

UBI ROAD 1 6366 2323

FAX NO

6841 1183

REFERENCE

PA/OD/0206/2022/JT

DATE

18-Mar-22

WIP

16206

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME

MR KHOO RONGWEN (QIU YONGWEN)

ADDRESS

73 ANCHORVALE CRESCENT

#09-07

SINGAPORE 544661

TELEPHONE

HP +65 96282254

TYPE OF CLAIM

OWN DAMAGE CLAIM

POLICY NO

1900108509-01

VEHICLE NO

SML 9740 X

MODEL CODE

AUDI A3 SEDAN 1.0 TFSI

MODEL YEAR

13/6/2019

CHZ C27820

ENGINE NO

CHASSIS NO

WAUZZZ8V0K1025220

MILEAGE

DATE IN

JOHNNY BOO / ALLAN WU

ESTIMATED BY

ACCIDENT DATE

17-Mar-22

PLACE OF ACCIDENT

DEFU STREET 1

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



55 UBI ROAD 1, SINGAPORE 408699 TEL : 6366 2323 FAX : 6841 1183 EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 9740 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT BUMPER WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N	\$ 360.00	×
2	TO DISMANTLE AND REINSTALL FRONT BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVE.		\$ 1,400.00	500/
3	TO RESPRAY FRONT BUMPER.		\$ 1,400.00	550/
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N	\$ 2,400.00	
5	TO RENEW LHS FRONT RIM WITH TYRE AND LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	\$ 560.00	320 /
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	/
	TOTAL LABOUR CHARGES	:	\$ 6,504.00	=



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 9740 X

				DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS	
1	SUSPENSION SUBERAME ? X NY	1	5	1,105.00		
2	BONDED RUBBER BUSHES 7 7 NO	1	5	116.00		
3	TRACK CONTROL ARM (Pht.)	1	\$	393.00	214.00	
4	STABILIZER	1	5		314.00	
5	FRONT WHEEL BEARING HOUSING - NC (AM)	1	5	451.00		
6	FRONT WHEELHUB BEARING - he (phi)	1	\$	627.00 / 553.00 /		
7	FRONT GUIDE JOINT - LH - M (Ph.T.)	1	5	134.00		
8	COUPLING ROD 7 × Nn	1	\$	105.00		
9	DRIVE SHAFT - LH 7 × nn	1	\$	1,517.00		
10	GAS SHOCK ABSOBER / OT (PM)	1	\$	281.00	224.80	
11	TRACK ROD / 17	1	\$	98.00	_	
12	TIE ROD END - LH / 19	1	\$	126.00		
13	STEERING GEAR 2 X NN	1	\$	5,538.00		
14	FRONT WHEEL HOUSING LINER - LH X M	1	\$	183.00		
15	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X	ากา	\$	93.00		
16	NOISE INSULATION 7 X MM	1	\$	376.00		
17	LHS RIM - FRONT & REAR / CHT / R	$\binom{2}{2}$		TBC		
18 1	LHS FRONT TYRE - TH (8016)	S/N		TBC 125	125.00	
19 5	SUNDRIES ? / Nec		\$	700.00	111-12-	
T	TOTAL SPARE PARTS	:	\$	12,396.00	•	
T	OTAL LABOUR CHARGES	:	\$	6,504.00		
C	RAND TOTAL	:	\$	18,900.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

Scanned with CamScanner

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG/CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Steve (LKK) 27/3/71, 11-11

OP-MAC

PJBL M

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO **BODY REPAIR MANAGER** **ALLAN WU CLAIMS CONSULTANT**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No Model No PA/00/0206/2022/JT

28-Mar-22 CHANG

1 of 1

SML 9740 X

AUDI A3 SEDAN 1.0 TEST

Quantity Description **Unit Price** Amount Parts REPAIR SET FOR STEERING BOX 50.00 39.92 \$ **GRAND TOTAL** \$ 50.00

For Premium Automobiles Pte Ltd

Authorised Sig. ature

Sten (LKK) 28/3/22