



REAR KNUCKLE ARM	<i>distorted</i>	1	\$810.60	\$810.60	✓
REAR STABILIZER BAR	<i>HH</i>	1	\$311.50	\$311.50	X
REAR STABILIZER LINK	<i>HH</i>	1	\$151.60	\$151.60	X
REAR TRAILING ARM	<i>distorted</i>	1	\$314.20	\$314.20	✓
REAR ASSIST ARM	<i>distorted</i>	1	\$342.20	\$342.20	✓
FRONT BUMPER COVER	<i>1st</i>	1	\$499.90	\$499.90	✓
LAMP ASSY, FOG, LH	<i>HH</i>	1	\$920.00	\$920.00	X
UNIT ASSY, HEADLAMP, LH (LED)	<i>minorly broken</i>	1	\$3,455.00	\$3,455.00	✓
HEAD LAMP PANEL (LH)	<i>HH</i>	1	\$240.10	\$240.10	X
TOP PANEL CENTRE	<i>HH</i>	1	\$364.98	\$364.98	X
TOP PANEL SIDE	<i>HH</i>	1	\$145.90	\$145.90	X
FENDER SUB-ASSY, FRONT LH	<i>SN</i>	1	\$945.30	\$945.30	✓
FRONT HOUSING ASSY	<i>HH</i>	1	\$958.30	\$958.30	X
FRONT FENDER SHIELD	<i>damaged</i>	1	\$38.00	\$38.00	✓
FRONT FENDER SHIELD CLIP	<i>HH</i>	1	\$14.90	\$14.90	✓
FRONT FENDER HYBRID EMBLEM, LH	<i>HH</i>	1	\$86.50	\$86.50	✓
BRACKET, FRONT SIDE PANEL, LH	<i>HH</i>	1	\$86.30	\$86.30	X
EXTENSION, FRONT FENDER, LH	<i>HH</i>	1	\$47.20	\$47.20	X
PROTECTOR, FRONT FENDER UPPER, LH	<i>HH</i>	1	\$46.10	\$46.10	X
GUSSET, FRONT FENDER APRON, LOWER LH	<i>HH</i>	1	\$34.90	\$34.90	X
MEMBER, FRONT APRON TO COWL SIDE, UPPER LH	<i>HH</i>	1	\$138.40	\$138.40	X
FRONT APRON TO COWL SIDE, LOWER FRT LH	<i>HH</i>	1	\$82.30	\$82.30	X
FRONT WINDSCREEN GLASS MOULDING	<i>HH</i>	1	\$208.60	\$208.60	X
FRONT WINDSCREEN GLASS MOULDING LOWER	<i>HH</i>	1	\$208.60	\$208.60	X
FRONT WINDSCREEN GLASS PILLAR	<i>Double</i>	1	\$343.10	\$343.10	✓
FRONT WHEEL RIM	<i>cut</i>	1	\$1,570.55	\$1,570.55	✓
FRONT WHEEL CAP (LH)	<i>broken</i>	1	\$177.70	\$177.70	✓
FRONT WHEEL HUB AND BEARING	<i>Done</i>	1	\$763.80	\$763.80	✓
FRONT SUSPENSION LOWER ARM (LH)	<i>distorted</i>	1	\$637.50	\$637.50	✓
FRONT SHOCK ABSORBER (LH)	<i>distorted</i>	1	\$401.80	\$401.80	✓
ABSORBER TOP MOUNTING	<i>HH</i>	1	\$196.20	\$196.20	X
FRONT DRIVE SHAFT (LH)	<i>HH</i>	1	\$1,764.00	\$1,764.00	X
RACK & PINION ASSY	<i>HH</i>	1	\$1,634.90	\$1,634.90	X
BAR, STABILIZER	<i>HH</i>	1	\$360.00	\$360.00	X
LINK ASSY, FRONT STABILIZER, LH	<i>HH</i>	1	\$199.00	\$199.00	X
KNUCKLE, STEERING, LH	<i>distorted</i>	1	\$580.80	\$580.80	✓
JOINT ASSY, LOWER BALL, FRONT (LH)	<i>distorted / Done</i>	1	\$199.98	\$199.98	✓
END SUB-ASSY, TIE ROD, LH	<i>HH</i>	1	\$159.30	\$159.30	X
SENSOR, SPEED, FRONT LH	<i>HH</i>	1	\$446.50	\$446.50	X
ENGINE UNDER COVER	<i>HH</i>	1	\$457.20	\$457.20	X
ENGINE UNDER COVER FRONT	<i>HH</i>	1	\$288.30	\$288.30	X
ENGINE CROSS MEMBER	<i>HH</i>	1	\$2,531.70	\$2,531.70	X
<b>SUB TOTAL</b>				<b>\$41,141.13</b>	
<b>LESS 20% <math>\rightarrow</math> 5%</b>				<b>\$8,228.23</b>	
<b>DISCOUNTED TOTAL</b>				<b>\$32,912.90</b>	
REAR BUMPER RUBBER MAT	<i>HH</i>	SN 1	\$50.00	\$50.00	X
REAR DOOR COMFORT & APPS STICKER	<i>HH</i>	SN 1	\$80.00	\$80.00	✓
REAR TYRE (LH)	<i>SN</i>	SN 1	\$216.00	\$216.00	X
FRONT WINDSCREEN GLASS SEALANT	<i>HH</i>	SN 1	\$40.00	\$40.00	X
FRONT WINDSCREEN IU BRACKET	<i>HH</i>	SN 1	\$30.00	\$30.00	X

2637.60

10,364.43

18,995.93

14,246.94

FRONT TYRE (LH) <del>HN</del>	SN	1	\$216.00	\$216.00	X
					155.00
<b>SUB TOTAL</b>					<b>\$632.00</b>
<b>Labour Charge</b>					
Panel Beating		1	\$1,800.00	\$1,800.00	1000/-
Spray Painting Charge		1	\$1,600.00	\$1,600.00	900/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$100.00	\$100.00	40/-
Towing Charge		1	\$80.00	\$80.00	HN
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	HN 150/-
Re-set Rear ABS System		1	\$400.00	\$400.00	HN
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	HN
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	HN
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System		1	\$200.00	\$200.00	HN
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	60/- 2680.00
Re-set Rear Power Window System		1	\$200.00	\$200.00	HN
Four Wheel Alignment		1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00	150/-
Re-set Frt ABS System		1	\$200.00	\$200.00	HN
Remove/Refix Radiator		1	\$90.00	\$90.00	HN
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	HN
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/-
<b>TOTAL LABOUR</b>					<b>\$6,840.00</b>
<b>ESTIMATE TOTAL</b>					<b>\$40,384.90</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

21/03/2022 @ 1700 hrs  
 Not returned  
 1/2 hr <sup>10</sup> 1 day.  
 you  
 JKK And  


17,081.94  
 4/5 15,300/-

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: