

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLP7825P/2203038

22nd March 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Not Authorised
22/3/22
4/55
9 days.

Date of Accident : 21st March 2022

Location : PIE

Third Party Claim Vehicle No : SMQ 1623 C

Repair Cost For Vehicle No : SLP 7825 P Toyota Altis

Repair sum \$ 6650

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover BUL	1	793.20	\$ 793.20 ✓
2	Rear boot cover emblem (logo) neu	1	50.70	\$ 50.70 ✓
3	Rear boot cover emblem (corolla) neu	1	42.00	\$ 42.00 ✓
4	Rear boot cover emblem (Altis) neu	1	45.60	\$ 45.60 ✓
5	Rear boot cover reflector L&RH one	2	203.70	\$ 407.40 ✓
6	Rear boot cover hinge L&RH surf/anti	2	69.90	\$ 139.80 ✓
7	Rear boot cover no plate garnish (chrome) one	1	242.90	\$ 242.90 ✓
8	Rear boot cover lock surf	1	399.50	\$ 399.50 ✓
9	Rear boot cover latch 11	1	52.90	\$ 52.90 X
10	Rear boot cover w/strip BVC	1	175.80	\$ 175.80 X
11	Rear lamp assy L&RH one	2	391.70	\$ 783.40 ✓
12	Rear end panel 3-16.00	1	670.00	\$ 670.00 ✓
13	Rear end panel inner garnish 7w1	1	241.90	\$ 241.90 ✓
14	Rear end panel inner garnish clips 11	1set	55.00	\$ 55.00 X
15	Rear boot floor panel R	1	818.10	\$ 818.10 X
16	Rear spare tyre board Torne	1	267.00	\$ 267.00 X
17	Rear bumper fascia D.D	1	556.40	\$ 556.40 ✓
18	Rear bumper clips neu	1set	55.00	\$ 55.00 ✓
19	Rear bumper reinforcement DD 395'	1	399.50	\$ 399.50 ✓
20	Rear bumper side retainer L&RH surf	2	105.80	\$ 211.60 ✓
21	Rear bumper bracket L&RH one	1	64.00	\$ 64.00 ✓
22	Rear fender L&RH R	2	1,149.80	\$ 2,299.60 X
				\$8,771.30

faulty block

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLP7825P/2203038

22nd March 2022

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 8,771.30
23	Rear fender cowling L&RH <i>11</i>	2	65.10	\$ 130.20 <i>X</i>
24	Rear fender cowling clips <i>11</i>	1set	55.00	\$ 55.00 <i>X</i>
25	Rear fender inner garnish L&RH <i>11</i>	2	315.50	\$ 631.00 <i>X</i>
26	Rear windscreen glass with moulding <i>11</i>	1	1,559.20	\$ 1,559.20 <i>X</i>
27	Antenna, electrical key sensor <i>203.90 cre ✓</i>			\$11,146.70
	Less		25%	\$ 2,786.68
				\$ 8,360.02
27	Rear camera (s/nett) <i>Sur</i>	1	880.00	\$ 880.00 <i>X</i>
28	Rear number plate (s/nett) <i>Surf</i>	1	50.00	\$ 50.00 <i>40</i>
29	Rear end panel sealer (s/nett) <i>Sur</i>	1	80.00	\$ 80.00 <i>50</i>
30	Rear boot floor insulation shield (s/nett) <i>11</i>	1	380.00	\$ 380.00 <i>X</i>
31	Rear bumper sensor (s/nett) <i>shaded</i>	1	380.00	\$ 380.00 <i>250</i>
32	Rear windscreen sealant (s/nett) <i>11</i>	1	60.00	\$ 60.00 <i>X</i>
				\$10,190.02

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding rear boot cover, rear fender L&RH, rear boot floor panel, rear end panel, remove & install all damage parts, straighten rear chassis & re-align body	\$ 2,880.00 <i>1400</i>
Remove & install rear windscreen glass <i>11</i>	\$ 140.00 <i>X</i>
Remove & refix rear bumper sensor	\$ 80.00 <i>50</i>
Remove & install rear seats, carpets, upholstery & etc	\$ 280.00 <i>50</i>
Tuff-kote on damage parts	\$ 200.00 <i>50</i>
Spray painting on damage parts	\$ 2,480.00 <i>1200</i>
Check all lighting after repairs	\$ 60.00 <i>30</i>
Anti rust proofing	\$ 250.00 <i>80</i>
Labour Charge	\$ 6,370.00
Total Amount	\$16,560.02
GST will be reflected in the final bills.	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5569.30
252
P- 4176.97
S.N- 340
2-2900
7416.97

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLP7825P/2203038

28th March 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 21st March 2022
Location : PIE
Third Party Claim Vehicle No : SMQ 1623 C
Repair Cost For Vehicle No : SLP 7825 P Toyota Altis

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Antenna, electrical key <i>one</i>	1	203.90	\$ 203.90
				<u>\$ 203.90</u>

GST will be reflected in the final bills.