

Vehicle Damage Assessment Report for [SLZ4243K]

Estimate Created: 25/03/2022 09:17 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 28/04/2023 23:06 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Previa
Engine Type			
License Plate Number	SLZ4243K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$550.00 WITH 2 WORKING
DAYS

Insurlogic 4 (28/04/2023 23:04)

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	150.00	0.00 %	150.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
FRONT RH DOOR	Medium	0.00	0.00 %	0.00
FRONT RH DOOR LOWER CHROME	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINT ON ALL AFFECTED AREA	Full spray	400.00	0.00 %	400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 150.00

Paint Labor Subtotal 400.00

Labor Subtotal 550.00

Summary

Repair Cost 550.00

Discount(0 %) (0.00)

550.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 550.00