

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203 - 154
DATE : 4-Mar-2022
POLICY NO. : BD P10143552R03
VEHICLE REG. NO. : SMJ2510A
VEHICLE MAKE : HONDA / SHUTTLE 1.5G CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper <i>de/</i>	1	\$ 1,200.00	\$ 1,200.00
2	Rear Bumper Clip <i>ne/</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer LH <i>X n</i>	1	\$ 50.00	\$ 50.00
4	Rear Bumper Retainer RH <i>X n</i>	1	\$ 50.00	\$ 50.00
5	Rear Bumper Grille RH <i>X n</i>	1	\$ 80.00	\$ 80.00
6	Rear Bumper Grille LH <i>? X n</i>	1	\$ 80.00	\$ 80.00
7	Rear Bumper Grille Inner Bracket RH <i>X n</i>	1	\$ 90.00	\$ 90.00
8	Rear Bumper Grille Inner Bracket LH <i>X n</i>	1	\$ 90.00	\$ 90.00
9	Rear Bumper Grille Reflector LH <i>X n</i>	1	\$ 70.00	\$ 70.00
10	Rear Bumper Grille Reflector RH <i>X n</i>	1	\$ 70.00	\$ 70.00
11	Rear Bumper Tow Eye Cover <i>X n</i>	1	\$ 50.00	\$ 50.00
12	Rear Tail Lamp LH <i>X n</i>	1	\$ 680.00	\$ 680.00
13	Rear Tail Lamp RH <i>X n</i>	1	\$ 680.00	\$ 680.00
14	Rear Tailgate Lamp RH <i>X n</i>	1	\$ 520.00	\$ 520.00
15	Rear Tail Lamp Panel LH <i>X n</i>	1	\$ 220.00	\$ 220.00
16	Rear Tail Lamp Panel RH <i>X n</i>	1	\$ 220.00	\$ 220.00
17	Rear Tailgate Lamp LH <i>X n</i>	1	\$ 520.00	\$ 520.00
18	Rear Tailgate <i>bu/</i>	1	\$ 1,500.00	\$ 1,500.00
19	Rear Tailgate Chrome Garnish <i>X n</i>	1	\$ 540.00	\$ 540.00
20	Rear Tailgate Shuttle Emblem <i>ne/</i>	1	\$ 80.00	\$ 80.00
21	Rear Tailgate Honda Emblem <i>ne/</i>	1	\$ 80.00	\$ 80.00
22	Rear Tailgate Lock <i>X n</i>	1	\$ 150.00	\$ 150.00
23	Rear Tailgate Absorber RH <i>X n</i>	1	\$ 150.00	\$ 150.00
24	Rear Tailgate Absorber LH <i>X n</i>	1	\$ 150.00	\$ 150.00
25	Rear Tailgate Inner Trim <i>? X n</i>	1	\$ 420.00	\$ 420.00
26	Rear / End Panel Garnish No. 10 <i>de/</i>	1	\$ 220.00	\$ 220.00
27	Rear Outlet Air Grille LH <i>X n</i>	1	\$ 60.00	\$ 60.00
28	Rear Outlet Air Grille RH <i>X n</i>	1	\$ 60.00	\$ 60.00
29	Rear / End Panel Garnish Cover No. 7 <i>? X n</i>	1	\$ 120.00	\$ 120.00
30	End Panel <i>bt/</i>	1	\$ 720.00	\$ 720.00
31	Rear Floor Panel Sink <i>X n</i>	1	\$ 1,500.00	\$ 1,500.00

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2203 - 154
DATE : 4-Mar-2022
POLICY NO. : BD P10143552R03
VEHICLE REG. NO. : SMJ2510A
VEHICLE MAKE : HONDA / SHUTTLE 1.5G CVTTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

KASUL - H990010068
6 days - 4/5 - 22/03/22 P1155
Resurvey after repair**ESTIMATE REPAIR COST**

100

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Rear Spare Tyre Board Cover No. 3 X n7	1	\$ 400.00	\$ 400.00
33	Rear Spare Tyre Board Tray No. 6 X n7	1	\$ 300.00	\$ 300.00
34	Rear Windscreen Molding n7	1	\$ 100.00	\$ 100.00
35	Rear Exhaust X n7	1	\$ 880.00	\$ 880.00
36	Rear Exhaust Rubber Mount X n7	2	\$ 50.00	\$ 100.00
Total Spare Parts				\$ 12,250.00
SPECIAL NETT				
37	Rear Windscreen Sealant n7	1	\$ 40.00	\$ 40.00
38	Rear Licence Plate X n7	1	\$ 35.00	\$ 35.00
39	Reverse Sensor cut	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 275.00
LABOUR				
40	Spray painting Rear Bumper, Tailgate, Both Rear Fender Including Blending	1	\$ 1,000.00	\$ 1,000.00
41	Remove, Replace and Repair Accident Affected Area	1	\$ 1,000.00	\$ 1,000.00
42	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
43	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
44	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 100.00	\$ 100.00
45	Remove and Refit Rear Windscreen	1	\$ 100.00	\$ 100.00
46	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
47	Anti-Rust Tuff Coat	1	\$ 40.00	\$ 40.00
48	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Oscar Pong

Total Labour \$ 2,570.00

Amount Before Excess \$ 15,095.00

Add GST @ 7% 1,056.65

Total Amount Payable \$ 16,151.65

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3160
N-240
L-1480
Suppl - 144
5024
20%
4019.20
4/5 - \$4,000

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Supplementary
Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203 - 154 (SUP)

DATE : 24-Mar-2022

POLICY NO. : BD P10143552R03

VEHICLE REG. NO. : **SMJ2510A**

VEHICLE MAKE : HONDA / SHUTTLE 1.5G CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Tailgate Weatherstrip nec	1	\$ 180.00	\$ 180.00
2				
Total Spare Parts				\$ 180.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
Total Labour				\$ -
Amount Before Excess				\$ 180.00
Add GST @ 7%				12.60
Total Amount Payable				\$ 192.60

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

180
20%
144