4/7/22, 9:31 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22002624/BVY3N2

Date: 07/04/2022

REFERENCE

Claimant Vehicle

Handling Insurer: ECICS Limited

ICS Limited Policy No:

•

No:

Insured Vehicle No: SMK7803S

Date of Loss: 23/02/2022 Nature of Claim: TP Claim No: DMPC2200081H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN7039Z

Make & Model: ISUZU NPR85UH5A, 3.0 D (M) Engine No: 4JJ11J9726

Reg. Date: 27/11/2014 (Man. Year: 2014) Chassis No: JAANPR85HE7100510

Colour: Red Odometer: 451077 km

Engine Capacity: 2999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00R16 Rear Tyre Size: 7.00R16

Front Left Side: Grenlander 5 mm Rear Left Side: Grenlander 5 mm Front Right Side: Grenlander 5 mm Rear Right Side: Grenlander 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,894.35	1,330.62	3,563.73	72.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,150.00	870.00	2,280.00	72.38
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,044.35	2,200.62	5,843.73	72.64
	Approved Total (Overridden) (S\$)		1,750.00		
	(S\$)	8,044.35	1,750.00	6,294.35	78.25
	+ GST 7.00/7.00% (S\$)	563.10	122.50	440.60	78.25
	Nett Amount (S\$)	8,607.45	1,872.50	6,734.95	78.25

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected:

23/03/2022 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN MING

AUTOCITY

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/7/22, 9:31 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Apr 2022)

Parts: N/A ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN7039Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP	Not Damaged	771.20 FL	*- FL
2	2		*TAILLAMP BRACKET	Not Damaged	596.60 FL	*- FL
3	1		*REAR NUMBER PLATE LAMP	Broken	78.00 FL	*67.50 FL
4	1		*SUNDRIES	Not Necessary	80.00 FS	*-FS
5	1		*REAR WOODEN STEP BAR	Broken	450.00 FS	*200.00 FS
6	1		*REAR END PANEL	Not Damaged	800.00 FS	*-FS
7	1		*REAR SAFETY BAR	Broken	1,600.00 FS	*480.00 FS
8	2		*REAR SAFETY BAR BRACKET	Bent	500.00 FS	*500.00 FS
9	1		*REAR NUMBER PLATE	Bent	80.00 FS	*30.00 FS
10	1		*REAR NUMBER PLATE BRACKET	Bent	300.00 FS	*70.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	Sub Total (S\$)	5,255.80	1,347.50
	- List Item Discount on L Items 25.00/25.00% (S\$)			361.45	16.88	
				Total Parts (S\$)	4,894.35	1,330.62
			Report was unsubmitted	during this print-out.		-

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	R&R REAR WOODEN STEP BAR	New	150.00	70.00
2	UPHOLSTERY	New	300.00	0.00
3	CHECK WIRING	New	100.00	0.00
4	PANEL BEATING	New	1,200.00	600.00
5	RUST PROOFING	New	200.00	0.00
6	SPRAY PAINTING	New	1,200.00	200.00
		Gross Labour Cost (S\$)	3,150.00	870.00
	Report w	vas unsubmitted during this print-out.		

< END OF ESTIMATES >