



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET			Ref: CC4/ASM22002625/Uea3q2 Date: 18/08/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBE 2522Y	Veh. Inspected	SKZ 2601K	
Policy No.	P1835750	Coverage (\$)	0.00	
Claim No.	S2M03WB7	Excess (\$)	0.00	
Assign From		Assign Date	22/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104546090	Colour	WHITE	
Odometer	102196 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/03/2022	Inspection Date	22/03/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			15 Working Days	