



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS3/ASM22002628/Gvy3 Date: 22/03/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 9611L	Veh. Inspected	SKS 9800T
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03W2C	Excess (\$)	0.00
	Assign From	ANG YVONNE	Assign Date	22/03/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	18/03/2022	Inspection Date	22/03/2022
	Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			