

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

ASSURED PROTECTION & CONSULTANCY PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not available
11 Amp @ 3050k
Recovery After Rain
5 days

Date: 21/3/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA VIOS / SMP 5854 G		
1 pc	rear boot lid <i>681.20</i>	<i>R</i> 738.60
1 pc	rear boot lid lock <i>152.20</i>	<i>Net</i> 198.50
1 pc	rear boot lid lock catch	<i>R</i> 75.80
1 pc	rear boot lid weather strip	<i>Net</i> 220.10
2 pcs	rear boot hinge	<i>R @ 145.20</i> 290.40
1 pc	rear boot emblem "E"	<i>Net</i> 30.10
1 pc	rear boot emblem "VIOS"	<i>Net</i> 38.30
1 pc	rear boot emblem logo	<i>Net</i> 58.60
1 pc	rear bumper <i>561.80</i>	<i>CM</i> 563.50
10 pcs	rear bumper clip	<i>Net</i> @ 3.50 35.00
2 pcs	rear bumper side retainer	<i>M/D</i> @ 47.60 95.20
2 pcs	rear bumper reflector	<i>N/S CM</i> @ 105.40 210.80
2 pcs	rear tail lamp assy	<i>N/S CM</i> @ 398.70 797.40
1 pc	rear end panel top garnish <i>165.80</i>	<i>M/D</i> 263.10
1 pc	rear end panel	<i>R</i> 316.20
1 pc	rear spare tyre top board <i>185</i>	<i>Net</i> 243.80
2 pcs	rear side foam <i>0126.20</i>	<i>N/S CM</i> @ 236.30 472.60
1 pc	number plate housing	<i>Net</i> s.nett 35.00
1 pc	number plate	<i>Net</i> s.nett 35.00
1 set	reverse sensor	<i>Net</i> s.nett 220.00
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		800.00
To apply waterproof sealant on affected areas.		50.00
To install reserve sensor.		60.00
To check wiring system.		30.00
To spray painting on affected areas		800.00
To apply rust proofing.		50.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Acknowledged by Repairer		Total: