

Not Notified
Reserve B4 paint
8684.60

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9231A**AAD2203-**

Vehicle No.:

22 MAR 2022

Chassis No.:

SHD9231A

Co UEN:

JTDKB3FU403083400

Vehicle Make:

200303878K

Vehicle Model:

TOYOTA

Date of Accident :

PRIUS

Third Party Insurer :

21/03/2022

Date of Registration :

SMC2756U/Auto & General

30/08/2019

PART**LIST**

1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	B ₁ 1,300.70	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	S ₁ 193.50	X
1	COVER, FRONT DOOR OUTSIDE HANDLE, LH	\$	L ₁ 17.90	X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	S ₁ 231.30	X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	R 110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	R 97.50	X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	M 13.30	—
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	M 43.50	—
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	M 26.30	—
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	S ₁ 926.00	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	L ₁ 238.30	X
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	S ₁ 1,339.30	X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	roll/warp 1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	S ₁ 193.50	X
1	COVER, REAR DOOR OUTSIDE HANDLE, LH	\$	S ₁ 17.90	X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	R 87.10	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	R 98.90	X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	M 21.90	—
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	M 34.90	—
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	M 15.40	—
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH	\$	L ₁ 926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	S ₁ 206.70	X
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	R L ₁ 594.80	X
1	COVER, REAR BUMPER	\$	R 442.60	X
1	FENDER SUB-ASSY, FRONT LH	\$	B ₁ 977.80	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2203-

SHD9231A

1 LINER, FRONT FENDER, LH	\$	Pr	202.50	X
1 PANEL SUB-ASSY, QUARTER, LH	\$	R	871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$	Rn	139.80	X
TOTAL	\$		10,664.40	
25%	\$		2,666.10	
	\$		7,998.30	

Special Nett

1 FENDER CLIP	\$	na	65.00	X
1 FENDER LINER CLIP	\$	na	65.00	X
1 FENDER CLIP	\$	na	65.00	X
1 FENDER LINER CLIP	\$	na	65.00	X
1 TYRE	\$	R	350.00	X
1 TYRE	\$	Rn	350.00	X
1 HUB CAP	\$	na CM	211.50	✓
1 HUB CAP	\$	na	211.50	✓
1SET DOOR WEATHERSTRIP CLIP	\$	na	65.00	X
1 REAR BUMPER CLIP	\$	na	65.00	X
1 FRT DOOR STICKER TRANSCAB	\$	na	100.00	60SN
1 REAR DOOR STICKER TEL. NO	\$	na	100.00	60SN
1SET CLIP, ROCKER PANEL MOULDING	\$	na	65.00	X
TOTAL	\$		1,778.00	

TOTAL PARTS \$ 9,776.30**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 700

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 1320

I: (\$

☐ Tech Invs (\$
☐ Weekend (\$

) Others

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9231A

AAD2203-

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	6d
To Check Electrical Lighting Concerned.	\$	170.00	2d
TOTAL	\$	3,590.00	
Over All Total	\$	13,366.30	

(PART-BY-PART) Repair Days 20 days

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

☐ Weekend (\$

☐ Others

TOTAL

Trans-cab Auto Services Pte Ltd

AAD2203-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9231A

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD9231A

JTDKB3FU403083400

200303878K

TOYOTA

PRIUS

21/03/2022

SMC2756U/

30/08/2019

SUPPLEMENTARY**PART****LIST**

1 RIM

\$ 1,900.10 ✓

TOTAL \$ 1,900.10**25% \$ 475.03****\$ 1,425.08**