



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 9945Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	NOT NECESSARY	1,568.40	-
1	REAR BOOTLID EMBLEM (HYUNDAI)	NOT NECESSARY	64.00	-
1	REAR BOOTLID EMBLEM (ELANTRA)	NOT NECESSARY	68.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	876.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	364.80	-
1	REAR END PANEL	NOT NECESSARY	546.00	-
	LESS 20% DISCOUNT		-697.44	-
			2,789.76	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR REVERSE SENSORS (SN)	NOT NECESSARY	250.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	300.00	-
1	EXHAUST TIP (SN)	NOT NECESSARY	150.00	-
1	REAR BUMPER LOWER MOULDING (SN)	NOT NECESSARY	400.00	-
1	REAR BOOTLID EMBLEM (ELITE) (SN)	NOT NECESSARY	66.00	-
			1,216.00	-
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	200.00
	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.	NOT NECESSARY	80.00	-
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		600.00	200.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	NOT NECESSARY	50.00	-
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	50.00	-

Report Ref No. CS/INC22002634/Rqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.	NOT NECESSARY	50.00	-
			1,490.00	400.00
GRAND TOTAL			5,495.76	400.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				400.00

Report Ref No. CS/INC22002634/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.