



**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

**Date Generated : 30/03/2022**
**User ID                      PohSuan**
**Section A - Accident Details**

Registration Number	SHB5925T
Case Reference Number	TAX/03/22/2040
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	NG BOON ANN (HUANG WEN'AN)
Type of Accident	Side Swipe
Accident Date and Time	18/3/2022 11:50 AM
Accident Reported Date and Time	18/3/2022 1:53 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114315
Special Instruction to ARC, if any	TP/ LEFT REAR PORTION
Prepared Date and Time	18/3/2022 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$3,256.88	\$0.00
Total Other Cost	\$380.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,068.88</b>	<b>\$700.00 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>RASUL (LKK) / AIG</b>
ARC / Surveyor Sign Off Date	<b>18/03/2022 3:28 PM</b>	<b>21/03/2022 10:28 AM</b>
Signature		
Remarks		part by part/resurvey after repair



**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/03/2022

User ID : PohSuan

		52592-47080	SEAL, RR BUMPER, LH	0.00	\$118.30	0.00	\$0.00	Replace	Not Given
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$485.60	100.00	\$0.00	Replace	Repair
		52461-47070	PAD, RR BUMPER, CTR	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		81555-47470	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP,	0.00	\$52.30	0.00	\$0.00	Replace	Not Given
<b>Total</b>					<b>\$4,063.00</b>		<b>\$0.00</b>		

X NN  
R  
X } NN  
X  
X

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

0.00  
+ 300.00  
+ 400.00  
-----  
700.00

