

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22002641/EVY3N2**Date:** 17/04/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO BUS PTE LTD Policy No: D20ML0003256
Date of Loss: 16/03/2022 Nature of Claim: OD Claim No: MFL2022D0001429

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC601K**
Make & Model: YUTONG ZK6127H, 8.8 D (M) Engine No: ISLE436021895473
Reg. Date: 05/07/2011 (Man. Year: 2010) Chassis No: LZYTATF63A1009122
Colour: Blue Odometer: 681950 km
Engine Capacity: 8849 cc
Market Value/New Car Price: S\$36,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,756.00	11,768.50	1,987.50	14.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	2,630.00	400.00	13.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,786.00	14,398.50	2,387.50	14.22
Approved Total (Overridden) (S\$)		11,500.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	15,286.00	10,000.00	5,286.00	34.58
+ GST 7.00/7.00% (S\$)	1,070.02	700.00	370.02	34.58
Nett Amount (S\$)	16,356.02	10,700.00	5,656.02	34.58

INSPECTION

Date of Assignment: 22/03/2022
Date Inspected: 23/03/2022 Inspected At: Connect3 (HQ)
566 Woodlands Road
Singapore 728697
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Apr 2022)	
Parts:	N/A	YUTONG ZK6127H 8.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC601K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Broken	3,800.00 F	*3,800.00 FL
2	1		*FRONT WINDSCREEN INNER SEAL	Necessary	650.00 F	*650.00 FL
3	1		*RH DRIVER SIDE GLASS	Broken	1,200.00 F	*1,200.00 FL
4	1		*FRONT RH REAR VIEW MIRROR ASSY	Broken	1,350.00 F	*1,350.00 FL
5	1		*FRONT PANEL	Dented	2,800.00 F	*2,800.00 FL
6	1		*FRONT PANEL INNER STRUCTURE	Dented	1,020.00 F	*1,020.00 FL
7	1		*FRONT RH HEADLAMP	Broken	1,450.00 F	*1,450.00 FL
8	1		*FRONT RH LINKAGE	Bent	980.00 F	*980.00 FL
9	1		*ERP	Necessary	26.00 FS	*26.00 FS
10	12		*SEALANT	Necessary	480.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,756.00	13,756.00
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	1,987.50
Total Parts (\$\$)	13,756.00	11,768.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE FRONT WINDSCREEN	New	800.00	800.00
2	LABOUR TO REMOVE RH DRIVER SIDE GLASS	New	200.00	200.00
3	LABOUR CHARGES	New	1,200.00	1,000.00
4	SPRAY PAINTING	New	800.00	600.00
5	CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$)			3,030.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >