

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT22/PC601K/ODC

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

QUOTATION

P-13,276
 -15%
 9957
 N-480
 L-2630
 13,067
 L/S-10,453.60
 =10,450

Dear Sir,

Cost of Repair to Vehicle PC601K

With reference to the above-mentioned, we are pleased to quote as follows:-


No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front windscreen / OR	1	3,800.00	3,800.00 /
2.	Front windscreen inner seal / NC	1	650.00	650.00 /
3.	RH driver side glass / OR	1	1,200.00	1,200.00 /
4.	Front RH rear view mirror assy / OR	1	1,350.00	1,350.00 /
5.	Front panel / DP	1	2,800.00	2,800.00 /
6.	Front panel inner structure / DP	1	1,020.00	1,020.00 /
7.	Front RH headlamp / OR	1	1,450.00	1,450.00 /
8.	Front RH linkage / BT	1	980.00	980.00 /
9.	ERP / NC	1	26.00	26.00 / net
10.	Sealant / NC	12	40.00	480.00 / net
11.	Labour to remove front windscreen	1	800.00	800.00 /
12.	Labour to remove RH driver side glass	1	200.00	200.00 /
13.	Labour charges	1	1,200.00	1000 / 1,200.00
14.	Spray painting	1	800.00	600 / 800.00
15.	Check wiring	1	30.00	30.00 /

		SUB-TOTAL	SS16,786.00
--	--	-----------	-------------

- Price before 7% gst

Thank you.
Yours faithfully,


Winnie Chai
HP: 9850-9666



Steve (LKK)

23/3/22, 9.00am

OD- 14 AL

Excess - ?

L/S

M AL M

8 d/s

Consultants hence notify
the following of the following:

- Before/after spray painting
- Damaged part(s) due to spray
- Third party involvement
- No damage to paint
- Supplementary details

is subject to final approval from the company.

Acknowledged by Repairer
Signature:
Date:

P - 13,250.00

-15%

11,262.50

NI - 506

L - 2630

14,398.50

L/S - 11,518.80

= 11,500