

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Mar 2022

Preliminary Advice

Vehicle No	: PC601K	Accident Date	: 16/03/2022
Make	: YUTONG ZK6127H	Policy No.	: D20ML0003256
Assignment Date	: 22/03/2022	Excess	: S\$0.00
Date of Inspection	: 23/3/2022	Est. Duration of Repair	: 8
Inspection At	: CONNECT3		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,786.00
Revised Amount	:S\$	16,386.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	16,386.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	17,216.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,784.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check