

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SMY8738S

Model: Mazda 3 Hybrid

QTY	Description	Repairer's Estimate	
	Spare Parts - List Items		
1	Rear bumper <i>de ✓</i>	\$	1,600.00 <i>997.40</i>
1	Rear end panel <i>X^N</i>	\$	1,600.00 <i>X</i>
1	Rear boot lock <i>X^N</i>	\$	500.00 <i>X</i>
1	Rear bumper sensor <i>? X^N</i>	\$	300.00 <i>X</i>
1	Reverse camera <i>X^N</i>	\$	250.00 <i>X</i>
1	Rear carplate light <i>? X^N</i>	\$	120.00 <i>X</i>
1	Carplate	\$	50.00
1	Carplate holder <i>3</i> cracked	\$	30.00 <i>335</i>

997.40

20%

797.92

\$ 4,450.00

S

4,450.00

c/f: S

AMT SS

Special Nett Items

S

S/N. Labour Charges

1

Remove and refit rear Panel

S

~~600.00~~ 200

2

Remove, refit and replaced damage and
check up rear electrical wiring

S

~~150.00~~ 60

3

Remove and refit inner garnishes trim to
assist repair

S

200.00 Xnn

4

To apply undercoating on replaced panel

S

120.00 Xnn

5

To Respray Painting.

S

~~600.00~~ 400

S

1,670.00

GRAND TOTAL

S

6,120.00

660

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Rasul
(Contact) 90010068
(Email) rasul@lkkauto.com
(Signature) R
(Date/Time) 23/03/22 @ 1620

Rasul ~~after~~ before paint
3 days / ~~1~~ 4/s

797.92
35.00
660.00

1492.92
20%
1194.33
4/s - 1,200

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: