

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 Anson Road # 16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6116
 Fax : 6224 - 7478 / 7175

DATE : 21.03.2022
 VEH NO : SCZ3338J
 MODEL : Mercedes S400i
 D O A : 10.03.2022
 YR REF :

Attn : Motor Claim Dept (Pls arrange vehicle survey)

RE : ESTIMATE FOR ACCIDENT REPAIR SCZ3338J (MERCEDES S400i)

<u>Item</u>	<u>Descriptions</u>	<u>Qty</u>	<u>Am't</u>
NO	LIST ITEMS		
1	Bonnet <i>Dented</i>	1	3,480.00 ✓ 1680
2	Bonnet Lock	2	86.00 ✗
3	Bonnet Hinges - LH & RH	2	596.00 ✗
4	Bonnet Damper - LH & RH	2	118.00 ✗
5	Bonnet Insulator	1	245.00 ✗
6	Front Grille <i>crushed</i>	1	795.00 ✓ 385
7	Bonnet Star <i>and</i>	1	115.00 ✓ 51
8	Front Bumper <i>Repair</i>	1	2,105.00 ✗
9	Front Windscreen <i>Shattered</i>	1	2,390.00 ✓ 1368
10	Wiper Blade <i>cut</i>	1 set	168.00 ✓ 100
11	Roof Panel <i>Repair</i>	1	2,475.00 ✗
12	Roof Panel Moulding - LH & RH <i>Repair</i>	2	710.00 ✗
13	Front Windscreen Pillar - RH <i>Dented</i>	1	8,618.00 596
14	Front Fender - RH <i>Repair</i>	1	1,388.00
15	Front Door - RH <i>Dented</i>	1	3,496.00 ✓ 1755
16	Front Door Glass Outer Moulding (Chrome) <i>restd.</i>	1	345.00 ✓ 161
17	Front Door Outer Chrome Moulding - RH <i>cut</i>	1	260.00 ✓ 95
18	Front Wing Mirror - RH <i>crushed</i>	1	1,090.00 ✓ 485
19	Front Wing Mirror Glass - RH <i>crushed</i>	1	1,060.00 ✓ 510
20	Rear Door - RH <i>Distorted</i>	1	3,690.00 ✓ 1805
21	Rear Window Glass - RH <i>Shattered</i>	1	980.00 ✓ 468
22	Rear Quarter Glass - RH <i>Shattered</i>	1	488.00 ✓ 208
23	Rear Door Glass Outer Moulding (Chrome) - RH <i>cut</i>	1	448.00 ✓ 218
24	Rear Door Outer Chrome Moulding - RH <i>Dented</i>	1	195.00 ✓ 84
25	Rear Door Channel - RH <i>Distorted</i>	1	360.00 ✓ 220

RE : ESTIMATE FOR ACCIDENT REPAIR SCZ3338J (MERCEDES S400i)

26	Rear Door Outer Handle - RH <i>new</i>	1	798.00 <i>x</i>
27	Roof Panel Pillar - RH <i>3 Repair</i>	1	1,266.00 <i>x</i>
28	Rear Fender Pillar - RH	1	1,889.00 <i>x</i>
29	Rear Door Curtain - RH <i>old</i>	1	<u>1,994.00</u> <i>975</i>

	41,648.00
Less 10%	<u>(4,164.80)</u>
	37,483.20

S/NET ITEMS

1	Front Number Plate <i>new</i>	1	45.00 <i>✓</i>
			<u>45.00</u>
	Total parts		<u>\$ 37,528.20</u>

LABOUR CHARGE

1	To knocking & pull out and renew damage parts	\$	3,000.00 <i>1600</i>
2	To putty and spray up paint work	\$	2,800.00 <i>2000</i>
3	To underseal	\$	150.00 <i>80</i>
4	To check wiring	\$	30.00 <i>✓</i>
5	To remove front windscreen	\$	150.00 <i>120</i>
6	To transfer door fittings (front & rear)	\$	300.00 <i>200</i>
7	To remove front & rear seats & upholstery	\$	280.00 <i>150</i>
8	Interior cleaning	\$	450.00 <i>300</i>
	Total labour	\$	<u>7,160.00</u>
	Grand Total	\$	<u>44,688.20</u>

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Adrian Lj
1/5 22/03/22
14 Days.
Not Authorized
Excess \$1000