

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road # 16-00
Springleaf Tower
Singapore 079909
Tel : 6389 - 6116
Fax : 6224 - 7478 / 7175

Estimate
DATE : 21.03.2022
VEH NO : SCZ3338J
MODEL : Mercedes S400i
D O A : 10.03.2022
YR REF : SNM22D201709

Veron.

Attn : Motor Claim Dept (Pls arrange vehicle survey)

Supplementary.

RE : SUPPLEMENTARY SCZ3338J (MERCEDES S400i)

Item	Descriptions	Qty	Amt
NO	LIST ITEMS		
1	Front Wing Mirror Signal Lamp - RH <i>Cracked.</i>	1	240.00 180.
2	Head Lamp - RH <i>cracked</i>	1	3,800.00 2500.
3	Front Door Black Garnish - RH <i>lit.</i>	1	480.00 200
4	Rear Door Black Garnish - RH <i>Distorted</i>	1	440.00 200.
5	Rear Door Inner Trim Board - RH <i>lit.</i>	1	3,410.00 1500
6	Rear Door Inner Trim Board Clips - RH <i>new</i>	1	60.00 30.
7	Roof Panel Inner Trim Board <i>Stained.</i>	1	5,880.00 1800.
8	Roof Panel Inner Trim Board Clips <i>new</i>	1	80.00 ✓

Sub Total 14,390.00
Add 10% 6990 1,439.00
15,829.00

plus 10%: 7139

LABOUR CHARGE

1	To remove and replace roof panel inner trim board	\$	800.00 300
Grand Total		\$	16,629.00

300

GST Will be reflected in the final bills

NOTE : -

Supplementary: 7439

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE