

8 Kaki Bukit Ave 4 #01-09, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

Vehicle Nos : SMX 7087Z

Made : Honda

Model : Vezel

Chassis No : _____

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear Bumper	1	\$ 797.90	\$ 760.50 797.90	BR✓
2	Rear Bumper Side Retainer RH	1	\$ 34.00	\$ ✓ 34.00	} NEC ✓
3	Rear Bumper Side Retainer LH	1	\$ 34.00	\$ ✓ 34.00	
4	Rear Bumper Reflector RH	1	\$ 161.00	\$ 121.00 161.00	BR✓
5	Rear Bumper Reflector LH	1	\$ 161.00	\$ 161.00	NDX
6	Rear Bumper Side RH	1	\$ 195.00	\$ ✓ 195.00	BR✓
7	Rear Bumper Side LH	1	\$ 195.00	\$ 195.00	NDX
8	Rear Bumper Centre Lower Cover	1	\$ 254.00	\$ 254.00	NDX
9	Rear Tailgate	1	\$ 1,250.00	\$ 877.90 1,250.00	DD✓
10	Rear Tailgate Lock Assembly	1	\$ 187.40	\$ 187.40	NDX
11	Rear Tailgate Lock Catch	1	\$ 76.80	\$ 76.80	NDX
12	Rear Tailgate Hinge RH	1	\$ 55.00	\$ 55.00	} NDX
13	Rear Tailgate Hinge LH	1	\$ 55.00	\$ 55.00	
14	Rear Tailgate Damper RH	1	\$ 132.65	\$ 132.65	} NDX
15	Rear Tailgate Damper LH	1	\$ 132.65	\$ 132.65	
16	Rear Tailgate Outer Garnish	1	\$ 220.00	\$ 220.00	NDX
17	Rear Emblem	1	\$ 39.70	\$ ✓ 39.70	} NEC ✓
18	Rear Tailgate "Vezel" Emblem	1	\$ 58.00	\$ ✓ 58.00	
19	Rear Tailgate Weatherstrip	1	\$ 140.80	\$ 140.80	NDX
20	Rear Tailgate Number Plate Lamp RH	1	\$ 48.00	\$ 48.00	} NDX
21	Rear Tailgate Number Plate Lamp LH	1	\$ 48.00	\$ 48.00	
22	Rear Tailgate Reflector Lamp RH	1	\$ 389.20	\$ 263.20 389.20	Cut✓
23	Rear Tailgate Reflector Lamp LH	1	\$ 389.20	\$ 389.20	} NDX
24	Rear Tailgate Inner Handle	1	\$ 46.00	\$ 46.00	
25	Rear Tailgate Inner Trim Board	1	\$ 388.00	\$ 388.00	} NEC ✓
26	Rear Tailgate Windscreen Moulding RH	1	\$ 45.00	\$ ✓ 45.00	
27	Rear Tailgate Windscreen Moulding LH	1	\$ 45.00	\$ ✓ 45.00	
28	Rear Tailgate Windscreen Moulding Lower	1	\$ 155.00	\$ 124.00 155.00	} NDX
29	Rear Tailgate Wiper Motor	1	\$ 512.00	\$ 512.00	
30	Rear Tailgate Stopper RH	1	\$ 18.00	\$ 18.00	
31	Rear Tailgate Stopper LH	1	\$ 18.00	\$ 18.00	} NDX
32	Rear End Panel	1	\$ 580.60	\$ 580.60	

33	Rear End Panel Top Garnish	1	\$	119.20	\$	119.20
34	Rear Spare Tyre Panel	1	\$	1,108.80	\$	1,108.80
35	Rear Spare Tyre Panel Top Board	1	\$	168.00	\$	168.00
36	Rear Spare Tyre Panel Tools Box Sponge	1	\$	310.00	\$	310.00
37	Rear Taillamp Assembly RH	1	\$	502.40	\$	502.40 482.40
38	Rear Taillamp Assembly LH	1	\$	502.40	\$	502.40
39	Rear Fender RH	1	\$	1,054.00	\$	1,054.00
40	Rear Fender LH	1	\$	1,054.00	\$	1,054.00
41	Rear Fender Wheel Arch Garnish RH	1	\$	235.00	\$	235.00 198.00
42	Rear Fender Wheel Arch Garnish LH	1	\$	235.00	\$	235.00
43	Rear Fender Inner Trim Board RH	1	\$	548.00	\$	548.00
44	Rear Fender Inner Trim Board LH	1	\$	548.00	\$	548.00
45	Rear Buzzer	1	\$	108.00	\$	108.00
46	Rear Smart Key Antenna Sensor	1	\$	162.40	\$	162.40
47	Rear Exhaust Pipe Assembly	1	\$	821.00	\$	821.00
48	Rear Exhaust Pipe Assembly Heat Shield	1	\$	154.00	\$	154.00
49	Rear Exhaust Pipe Mounting	2	\$	55.00	\$	110.00

Parts Sub Total : \$ ~~14,602.10~~ 3,277.90

20% Discount \$ ~~2,920.42~~ 655.54

PARTS TOTAL : \$ 11,681.68

2622.16

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$	50.00 50.00
2	Rear Bumper Clips - Set	1	\$	50.00 30.00
3	Rear Taillamp Clips - Set	1	\$	50.00 30.00
4	Rear Tailgate Reflector Lamp Clips - Set	1	\$	50.00
5	Rear End Panel Top Garnish Clips - Set	1	\$	50.00
6	Rear Fender Inner Shield Clips - Set	1	\$	80.00
7	Rear Fender Inner Trim Board Clips - Set	1	\$	100.00
8	Rear Tailgate Sealant	1	\$	150.00 30.00
9	Rear End Panel Sealant	1	\$	150.00
10	Rear Spare Tyre Panel Sealant	1	\$	150.00
11	Rear Tailgate Windscreen Glass Sealant	1	\$	150.00 40.00
12	Rear Tailgate Inner Trim Board Clips - Set	1	\$	50.00 30.00
13	Rear Tailgate Outer Garnish Clips - Set	1	\$	50.00 30.00
14	Rear Fender Wheel Arch Garnish Clips - Set	1	\$	100.00 30.00
15	Rear Bumper Reverse Sensor - Set	1	\$	350.00 200.00
16	Rear Tailgate Reverse Camera	1	\$	500.00

SPECIAL NETT TOTAL : \$ 2,080.00

420.00

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts	\$ 600.00 1,800.00 ✓
2	To Spray Paint Affected Areas	\$ 400.00 1,800.00 ✓
3	Wiring & Bulb Check	\$ 100.00 NNX
4	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120.00 150.00 ✓
5	To Transfer Tailgate Mechanism	\$ 80.00 150.00 ✓
6	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00 NNX
7	To Remove & Refix Rear Bumper Reverse Sensor	\$ 60.00 120.00 ✓
8	To Remove & Refix Rear Exhaust Pipe	\$ 150.00 NNX
9	To apply anti rust on affected parts	\$ 100.00 } NNX
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00 }
11	To Conduct Water Leak Test	\$ 100.00 }
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00 }
LABOUR TOTAL :		\$ 5,250.00

Survey + Resurvey

23/3/2022

1328 hrs

TGum Min

PARTS TOTAL :	\$	11,681.68
SPECIAL NETT TOTAL :	\$	2,080.00
LABOUR TOTAL :	\$	5,250.00
GRAND TOTAL :	\$	19,011.68

1260.00

Lump sum Repair
Repair days 6

Parts	2622.16
SN	420.00
Labour	1260.00
	4302.16
@ 20%	860.43
	3441.73

LS 3,450/-

TGum Min
1/4/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: