

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

22 March 2022

TPA 19.
Ashes.

WD D2073482F041029

QUOTATION FOR ACCIDENT REPAIR OF SJM8290P MERCEDES BENZ E200CGI COUPE THIRD PARTY INSURER: AIG

S/No.	Parts List	Qty	Amount (\$)
1.	Front bonnet <i>Rep</i>	1	\$ 2246.00 <i>x</i>
2.	Front bonnet logo <i>neu</i>	1	\$ 85.00 <i>✓</i>
3.	Front bonnet chrome <i>neu</i>	1	\$ 188.00 <i>x</i>
4.	Front headlamp L/R <i>cracked LH</i>	2	2385.00 \$ 4770.00 <i>2385</i>
5.	Front headlamp top garnish L/R <i>neu</i>	2	60.00 \$ 120.00 <i>x</i>
6.	Front headlamp nozzle L/R <i>neu</i>	2	180.00 \$ 360.00 <i>x</i>
7.	Front headlamp nozzle cover L/R	2	65.00 \$ 130.00 <i>+</i>
8.	Front bumper <i>ton</i>	1	\$ 1450.00 <i>✓</i>
9.	Front bumper no plate garnish <i>del</i>	1	\$ 155.00 <i>✓</i>
10.	Front bumper towing cover <i>neu</i>	1	\$ 52.00 <i>+</i>
11.	Front bumper lower chrome L/R <i>neu</i>	2	170.00 \$ 340.00 <i>+</i>
12.	Front bumper lower chrome centre	1	\$ 210.00 <i>+</i>
13.	Front bumper lower grille	1	\$ 85.00 <i>x</i>
14.	Front parking sensor	4	280.00 \$ 1120.00 <i>+</i>
15.	Front parking sensor holder	4	40.00 \$ 160.00 <i>x</i>
16.	Front bumper side retainer L/R	2	58.00 \$ 116.00 <i>x</i>
17.	Front bumper inner sponge <i>cracked</i>	1	\$ 140.00 <i>✓</i>
18.	Front bumper reinforcement beam <i>neu</i>	1	\$ 576.00 <i>+</i>
19.	Brace panel <i>neu</i>	1	\$ 130.00 <i>+</i>
20.	Front support panel top garnish <i>neu</i>	1	\$ 135.00 <i>+</i>
21.	Front grille <i>cracked</i>	1	\$ 425.00 <i>✓</i>
22.	Front grille logo base <i>neu</i>	1	\$ 170.00 <i>+</i>
23.	Front grille "logo" emblem <i>neu</i>	1	\$ 130.00 <i>✓</i>

Subtotal before discount \$ 13293.00

Discount 10% \$ 1329.30

Subtotal 1 \$ 11,963.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ate:

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

22 March 2022

QUOTATION FOR ACCIDENT REPAIR OF SJM8290P MERCEDES BENZ E200CGI COUPE THIRD PARTY INSURER: AIG

<u>S/NETT</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Front number plate <i>But</i>	1	\$ 25.00 ✓
2.	Front number plate garnish <i>del</i>	1	\$ 50.00 30
3.	Front bumper clip <i>del</i>	1	\$ 50.00 ✓
S/Nett Total			\$ 125.00

Front Labour

To check wiring and rectify electrical faults where necessary

To straighten, repair, realign on front affected area and replace damaged parts

To spray painting on affected area

Total Labour Cost \$ 2060.00

Total Cost Of Repairs(Total cost of parts + Total labour cost) **\$ 14,148.70**

Adrian Lj
L/S 23/03/22

03 days

total: 5623
L/S: 4.5K