



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300051

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 04/01/2023
Reference CC6/CTI22002652/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 6831M
Insured Veh. SKN 3333R
Claim No. SNM22D201984/C02
Policy No. DMPCSNW00049172201
Accident Date 22/03/2022
Inspection Date 23/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22002652/Dpa3q2 Date: 04/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKN 3333R	Veh. Inspected	SHD 6831M	
Policy No.	DMPCSNW00049172201	Coverage (\$)	0.00	
Claim No.	SNM22D201984/C02	Excess (\$)	0.00	
Assign From		Assign Date	23/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E220	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2120012B315369	Colour	WHITE	
Odometer	613981 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	CITI	5 mm	
L/H Front Tyre	225/55 R16	CITI	5 mm	
R/H Rear Tyre	225/55 R16	CITI	5 mm	
L/H Rear Tyre	225/55 R16	CITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2022	Inspection Date	23/03/2022	
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6831M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER ASSY, FRT	TORN / CUT	1,890.50	1,890.50
1	BUMPER REINFORCEMENT, FRT	BENT / DENTED	1,158.00	1,158.00
2	BUMPER BRACKET, FRT/LH/RH @\$95.00	NOT NECESSARY	190.00	-
2	BUMPER ABSORBER, FRT/LH/RH @\$295.00	NOT NECESSARY	590.00	-
2	BUMPER SIDE BEAM, FRT/LH/RH @\$26.90	NOT NECESSARY	53.80	-
1	BUMPER FRAME, FRT/CENTRE	CRACKED	389.00	389.00
2	BUMPER FRAME, FRT/LH/RH @\$168.00	SERVICEABLE	336.00	-
1	BUMPER SPONGE, FRT/CENTRE	TORN	285.00	285.00
2	BUMPER SPONGE, FRT/LH/RH @\$250.00	NOT FITTED	500.00	-
2	BUMPER SPONGE EXTENSION , FRT/LH/RH @\$105.00	NOT FITTED	210.00	-
1	BUMPER TOWING COVER, FRT	CUT	68.00	68.00
1	BUMPER GRILLE, FRT/CENTRE	BROKEN	290.50	290.50
1	BUMPER INNER CLIP, FRT	SERVICEABLE	22.00	-
1	LICENSE PLATE TRIM COVER, FRT	DEFORMED / DENTED	155.00	155.00
2	HEADLAMP (E6) @\$3957.00	MTG CRACKED	7,914.00	7,914.00
2	HEAD LAMP BRACKET (LH/RH) @\$300.00	TO REPAIR SEE LABOUR	600.00	-
1	RADIATOR TOP PANEL, FRT	TO REPAIR SEE LABOUR	330.50	-
2	HEAD LAMP PANEL (LH/RH) @\$480.00	TO REPAIR SEE LABOUR	960.00	-
1	RADIATOR GRILLE (E6)	BROKEN	1,220.00	1,220.00
1	RADIATOR GRILLE ADJUSTER BRACKET	BROKEN	685.70	685.70
1	BONNET ASSY	BENT	2,850.60	2,850.60
2	BONNET STOPPER SPRING (LH/RH) @\$385.00	SERVICEABLE	770.00	-
2	BONNET LOCK SENSOR (LH/RH) @\$285.50	NOT NECESSARY	571.00	-
1	BONNET LOCK, TOP	DAMAGED / BENT	94.00	94.00
2	BONNET LOCK LOWER @\$92.00	SERVICEABLE	184.00	-
1	BONNET CATCH HANDLE	TO REPAIR SEE LABOUR	29.50	-
1	BONNET LOCK BRACE PANEL	TO REPAIR SEE LABOUR	64.80	-

Report Ref No. CC6/CTI22002652/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET AIR INLET GRILLE	BROKEN	269.25	269.25
1	RADIATOR ASSY	NOT NECESSARY	1,345.00	-
1	RADIATOR FAN BLOWER ASSY	NOT NECESSARY	1,385.40	-
1	RADIATOR SHROUD	NOT NECESSARY	1,225.60	-
1	RADIATOR AIR BAFFLE, TOP	NOT NECESSARY	80.00	-
1	RADIATOR AIR BAFFLE, LOWER	NOT NECESSARY	125.90	-
20	RIVET RADIATOR/BUMPER @\$4.00	NOT NECESSARY	80.00	-
1	AIRCON CONDENSER	NOT NECESSARY	1,235.80	-
1	ENGINE UNDER COVER FRONT (ADDITIONAL)	BROKEN	485.00	485.00
	LESS 10% DISCOUNT		-2,864.39	-1,775.46
			25,779.46	15,979.09
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE, FRT (MERC TAXI) (SN)	DISLODGE	50.00	45.00
1	COOLANT (SN)	NOT NECESSARY	65.00	-
			115.00	45.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF HEAD LAMP BRACKET (LH/RH), RADIATOR TOP PANEL, FRT, HEAD LAMP PANEL (LH/RH), BONNET CATCH HANDLE AND BONNET LOCK BRACE PANEL.		1,600.00	700.00
	SPRAY PAINTING CHARGE.		1,400.00	500.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	20.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,080.00	1,250.00
GRAND TOTAL			29,974.46	17,274.09



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,500.00
---	--	--	------------------

Report Ref No. CC6/CTI22002652/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6831M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6831M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 6831M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

