

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SFW 3357 J**

Model : Mitsubishi Colt Plus

Year : 2010

Chassis No : JMYLTZ23W9Z000448

After-Paint:

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2010

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 978.00	\$ 835.00 978.00	DDV
2	Tailgate logo	1	\$ 68.00	\$ 42.00 68.00	NECV
3	Tailgate weatherstrip	1	\$ 281.20	\$ 191.00 281.20	TNV
4	Tailgate outer garnish	1	\$ 285.00	\$ 285.00	NDX
5	Tailgate inner handle	1	\$ 78.00	\$ 78.00	
6	Tailgate inner lock	1	\$ 372.00	\$ 372.00	JMV
7	Tailgate lamp RH 1	2	\$ 386.00 487.00	\$ 386.00 974.00	BRV
8	Tailgate inner trim board	1	\$ 449.00	\$ 274.00 449.00	BRV
9	Tailgate windscreen moulding top	1	\$ 147.00	\$ 68.00 147.00	NECV
10	Tailgate windscreen moulding bottom	1	\$ 79.00	\$ 68.00 79.00	NECV
11	Rear bumper	1	\$ 891.00	\$ 592.00 891.00	BRV
12	Rear bumper side retainer	2	\$ 61.00 161.90	\$ 122.00 323.80	NECV
13	Rear bumper bracket	2	\$ 142.70	\$ 285.40	NSX
14	Rear bumper reflector RH 1	2	\$ 27.00 168.00	\$ 27.00 336.00	BRV
15	Rear end panel inner	1	\$ 496.00	\$ 296.00 496.00	DDV
16	Rear end panel outer	1	\$ 568.00	\$ 268.00 568.00	BRV
17	Rear end panel top garnish	1	\$ 184.00	\$ 166.00 184.00	NDX
18	Rear end panel air vent	1	\$ 64.00	\$ 64.00	DDV
19	Spare tyre panel	1	\$ 945.00	\$ 856.00 945.00	NDX
20	Spare tyre panel top cover	1	\$ 385.00	\$ 385.00	
21	Spare tyre panel tray	1	\$ 465.00	\$ 465.00	
22	Rear fender RH	1	\$ 748.00	\$ 748.00	DDV
23	Rear fender inner trim board RH 1	2	\$ 489.73	\$ 179.00 979.46	BRV
24	Rear fender side glass moulding	1	\$ 188.00	\$ 188.00	NECV
25	Taillamp RH 1	2	\$ 325.00 586.00	\$ 325.00 1,172.00	BRV
26	Exhaust silencer	1	\$ 862.00	\$ 362.00 862.00	BTV
27	Exhaust mounting	2	\$ 25.00 46.00	\$ 50.00 92.00	NECV

28	Front bumper	1	\$	983.60	\$ 834.00	983.60	BRV
29	Front bumper side retainer	2	\$	24.00 79.20	\$ 48.00	158.40	NECV
30	Front bumper reinforcement	1	\$	598.60	\$	598.60	NDX
31	Front bumper inner lower garnish	1	\$	382.60	\$ 176.50	382.60	BRV
32	Front bumper logo	1	\$	68.00	\$ 32.00	68.00	NECV
33	Front support panel	1	\$	786.30	\$	786.30	NDX
				Parts Sub Total :	\$ 7505.50	15,673.36	
				10% Discount :	\$ 750.55	1,567.34	
				PARTS TOTAL :	\$	14,106.02	
				6754.95			

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 50.00	\$ 50.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00	NEC ✓
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00	
4	Tailgate lamp clips RH 1	2	\$ 50.00	\$ 20.00 100.00	
5	Tailgate lamp inner seal RH 1	2	\$ 60.00	\$ 20.00 120.00	
6	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	NNY
7	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00	
8	Tailgate windscreen inner seal	1	\$ 60.00	\$ 20.00 60.00	
9	Tailgate windsreen primer & cleaner	1	\$ 80.00	\$ 80.00	NEC ✓
10	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	
11	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00	
12	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00	NNX
13	Spare tyre panel sealant	1	\$ 100.00	\$ 30.00 100.00	
14	Rear fender sealant	1	\$ 100.00	\$ 100.00	
15	Rear fender inner trim board clips	2	\$ 50.00	\$ 30.00 100.00	NEC ✓
16	Rear fender side glass sealant	1	\$ 100.00	\$ 20.00 100.00	
17	Rear fender side glass inner seal	1	\$ 60.00	\$ 60.00	
18	Rear fender side glass primer & cleaner	1	\$ 80.00	\$ 80.00	NNX
19	Taillamp clips RH 1	2	\$ 50.00	\$ 20.00 100.00	NEC ✓
20	Taillamp inner seal RH 1	2	\$ 60.00	\$ 20.00 120.00	
21	Rear reverse camera	1	\$ 480.00	\$ 480.00	NNX
22	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00	SC ✓
23	Front & rear number plate w/casing REAR 1	2	\$ 80.00	\$ 30.00 160.00	BTV
24	Front bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC ✓
25	Front support panel sealant	1	\$ 100.00	\$ 100.00	NNX
SPECIAL NETT TOTAL :				\$ 660.00 2,960.00	

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00	150.00
2	R&R tailgate windscreen	\$ 120.00	250.00
3	R&R rear bumper reverse sensor	\$ 60.00	100.00
4	R&R exhaust silencer	\$ 50.00	150.00
5	R&R rear fender side glass	\$ 60.00	250.00
6	Rear Upholstery	\$	900.00
7	Rear check wiring	\$	100.00
8	Rear panel beating	\$ 1200.00	1800.00
9	Rear rust proofing	\$	200.00
10	Rear spray painting	\$ 1000.00	1800.00
11	Front upholstery	\$	200.00
12	Diagnostic reset fault code	\$	300.00
13	Front check wiring	\$	100.00
14	Front panel beating	\$ 250.00	800.00
15	Front rust proofing	\$	100.00
16	Front spray painting	\$ 200.00	800.00
LABOUR TOTAL :		\$	7,400.00

✓ N/A

✓ N/A

✓ N/A

✓ N/A

✓ N/A

✓ N/A

✓ N/A

✓ N/A

Survey
1520 hrs
TGM Min
23/3/2022

Resurvey
24/3/2022
1245 hrs
Min

2970.00

PARTS TOTAL : \$ 14,106.02

SPECIAL NETT TOTAL : \$ 2,960.00

LABOUR TOTAL : \$ 7,400.00

GRAND TOTAL : \$ 24,466.02

Lump sum repair
Repair days 14

Parts 6754.95
SN 660.00
Labour 2970.00
10,384.95
2,076.99
8,307.96

LS 8300/2

TGM Min
28/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: