

Repair Estimate

Thiam Heng Huat Pte Ltd


176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA NOAH HYBRID
 Engine/Chassis No.: ZWR800390297
 Date of accident:
 Damaged area: O/S

Date: 22/03/2022

Claim Type: TP

VRN: SMX2713H



*Not authorized
 11 Png 82400h
 Put away After Paint*

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Slide door o/s	1	\$ 1,809.00	\$ 1,809.00
2	Slide door window channel o/s	1	\$ 176.00	\$ 176.00
3	Slide door weatherstrip o/s	1	\$ 258.00	\$ 258.00
4	Slide door outer handle o/s	1	\$ 371.00	\$ 371.00
5	Slide door motor o/s	1	\$ 966.00	\$ 966.00
6	Slide door lock o/s <i>358.20</i>	1	\$ 396.00	\$ 792.00
7	Slide door roller lower o/s	2	\$ 169.00	\$ 338.00
8	Slide door roller upper o/s	2	\$ 128.00	\$ 256.00
9	Rear fender roller rail o/s	1	\$ 199.00	\$ 199.00
10	Rear fender o/s	1	\$ 1,267.00	\$ 1,267.00
11	Rear fender glass moulding o/s	1	\$ 289.00	\$ 289.00
12	Slide door pillar black sticker o/s	2	\$ 48.00	\$ 96.00
13	Slide door inner trim board o/s	1	\$ 573.00	\$ 573.00
14	Slide door window motor o/s	1	\$ 335.00	\$ 335.00
15	Slide door window regulator o/s	1	\$ 298.00	\$ 298.00
16	Slide door window inner trim o/s	1	\$ 145.00	\$ 145.00
17	Slide door close sensor o/s	1	\$ 798.00	\$ 798.00
18	Slide door outer handle switch o/s	1	\$ 128.00	\$ 128.00
Subtotal				\$ 9,094.00
List discount				25.00%
Total				\$ 6,820.50

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Slide door inner trim board clips o/s	8	\$ 5.50	\$ 44.00
2	Rear fender glass sealant o/s	1	\$ 100.00	\$ 100.00
3	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 194.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect door wire harness of electrical component to facilitate repairs, reconnect and check functions of power windows.	0.5	\$ 100.00
3	To remove and refit o/s slide door components to facilitate replacement, check alignment.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To remove and refit o/s rear fender glass to facilitate repair.	0.75	\$ <i>vv</i> 150.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,650.00
Estimate Grand Total			\$ 9,664.50

2501

206

601

2506

X

306