

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Douglas Ong Chu Chong

Date: 12 May 2022

Preliminary Advice

Insured	: SLP3829E		
Vehicle No			
TP Vehicle No	: YP2396P	Accident Date	: 19/03/2022
Make	: MITSUBISHI CANTER	Assignment Date	: 23/03/2022
Date of Inspection	: 01/04/2022	Est. Duration of Repair	: 3
Inspection At	: TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,860.00
Revised Amount	:S\$	3,200.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,200.00

Lump Sum Repair	:S\$	2,550.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.