Not Nothain

AAD2203-

## **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5707X

	Vehicle No.:		SHD57	707X
	Chassis No.:		JTDKB3	3FUX03077391
	Co UEN: 2 2 MAR 2022		200303	3878K
	Vehicle Make:		TOYOT	·A
	Vehicle Model:		PRIUS	
	Date of Accident :		19603/	2022
	Third Party Insurer:		5 2632	2CD /AIG.
	Date of Registration:		12/12/	
	PART			LIST
1	COVER, REAR BUMPER		\$	CM 442.60 -
1	COVER, REAR BUMPER, LOWER		\$	In 15.40 X
1	GUARD, REAR BUMPER, CENTER		\$	nu 576.30 ~
1	REINFORCEMENT SUB-ASSY, REAR BUMPER		\$	₹ 332.70 <b>X</b>
1	FILLER, REAR BUMPER EXTENSION, RH		\$	Mac 123.70
1	COVER, BACK DOOR TRIM		\$	1 24.90 X
1	PANEL SUB-ASSY, BODY LOWER BACK		\$	N 650.30 X
1	LENS AND BODY, REAR LAMP, RH (LOWER)		\$	CM 502.00
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)		\$	5 451.80 X
1	PANEL SUB-ASSY, QUARTER, RH		\$	N 871.50 X
	Т	OTAL	\$	3,991.20
		25%	\$	997.80
			\$	2,993.40
Special Nett				
1SET	PARKING AID		\$	5- 700.00 X
1	REAR BUMPER CLIP		\$	Ma 65.00 basa
1	REAR TAIL LAMP CLIP		\$	na ma 65.00 -
1	END PANEL INNER TRIM CLIP		\$	20 60.00 X
2	WINDSCREEN SEALANT		\$	~~ 150.00 X
1	WINDSCREEN MOULDING		\$	~~ 200.00 X
1	WINDSCREEN INNER SPONGE SEAL		\$	~~130.00 X
	TO	OTAL	\$	670.00
	TOTAL P	ARTS	\$	8,543.40

**LABOUR** 

## **Trans-cab Auto Services Pte Ltd**

AAD2203-

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD5707X

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	N~ 250.00 ×
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00 2800
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	N~ 380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 2001
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of rear fender panel fittings, attachment and perform water seepage test.  TOTAL	\$ <b>\$</b>	5,990.00 X
Over All Total	\$	17,526.80
(PART-BY-PART) Repair Days		20 Days 2 day,
		Iday,

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: