

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 23 May 2022

Preliminary Advice

Insured : GBF9723H
Vehicle No
TP Vehicle : SMY3666Z
No
Make : PORSCHE CAYMAN
Date of : 17/05/2022
Inspection
Accident Date : 22/01/2022
Assignment Date : 23/03/2022
Est. Duration of : 3
Repair
Inspection At : IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ)
25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB
SINGAPORE 417800

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,837.60
Revised Amount	:S\$	5,291.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,291.40

Lump Sum Repair	:S\$	4,200.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.