

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSG 22002665/14943**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SMV 3666Zat Workshop m/s Imprian.

of _____

Insured: G5F 9723H

Policy No. _____


Claims No. 268740

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$150k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5996

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV 3666Z Yr Regn: 24/11/10Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or SPDKMake: Arsche Cayman c.c. 3436Colour: Grey/white A/C: Insured / Std / NI / NASp. Reading: 66843 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP0222982BU 770129Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/35 R19R: 265/35-R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 22/01/22 D.O.I. 17/5/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRecr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 19k.Corr note 31-08-2030 LTA 82734817/6/22 W rep sticker informed shawn 4/5 \$4200 (Red \$16637.60, 80%)23/05/22 @ 4.53pm revised 3 email to Douglas Org to seek mandate at \$4200, 3 days
16/06/22 @ 4.41pm Douglas Org informed that the mandate approved by email.

Date/Time, File Pass to?

☐

: Preli. Report

1) 17/6/22 W rep sticker☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: MPR-TPLump Sum / I.B.I. (\$) 4200)

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

11 Apr 2022

Vehicle No.: SMY 3666 Z

Model: PORSCHE CAYMAN

Not Authorized
Lumeras
17/5/22
1/5 \$ 4200
3 days

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Rear spoiler	11 \$ 1,023.00 X
2	Rear taillamps	11 \$ 3,225.20 X
1	Rear end panel	11 \$ 1,313.40 X
1	Rear bumper <i>sport</i>	2821 11/2e \$ 3,877.60 ✓
2	Rear bumper brackets	11 \$ 554.40 X
1	Rear bumper clip (1 set)	80 11 \$ 187.00 ✓
1	Rear bumper inner sponge	11 \$ 121.00 X
1	Rear bumper lower <i>exhaust heat shield</i>	485.00 11 \$ 545.60 ✓
1	Rear bumper reinforcement	11 \$ 946.00 X
2	Rear bumper side retainers	11 \$ 954.80 X
4	Rear bumper PDC sensors <i>@ 260</i>	11 \$ 2,156.00 12C
		\$ 14,904.00
		Less 10% \$ 1,490.40
		\$ 13,413.60

Special Nett Items

1	Rear number plate set	one \$ 250.00 80
1	Rear bumper "3M" sticker	11 \$ 1,200.00 500
1	Rear exhaust tail pipe set	11 \$ 2,244.00 X
		\$ 3,694.00

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 150.00 60
3	To remove and refit rear reverse sensor.	\$ 200.00 50
4	To apply undercoating.	\$ 11 200.00 X
5	Panel beating.	\$ 1,600.00 800
6	To re-spray painting on the affected areas	\$ 1,500.00 500
		\$ 3,730.00

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date:

Grand Total : \$ 20,837.60

2-3646
108
3281.4
1791.4