



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPOPE 408611, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tan Li Kai (Chen Likai) 260 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681 Mobile: 90073103		
			Document No 0				
			Document Date 11/04/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	0	21685	67/DS/SMV0775C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU80J060567		2ZR2H9377	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLD3959B ACC DATE 21/03/2022 DRIVE IN 21/03/2022 DATE IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓	30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				✓	183.18
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓	180.00
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓	180.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)- REAR END PANEL				✓	60.00
6	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET				✓	360.00
7	S	GARNISH AND TRIMMING TO ASSIST REPAIR				✓	180.00
8	B	BP-SUBLET TO RESET ECU AND REPROGRAMME				✓	1440 4320.00
9	B	BP-LAB2 REPLACE REAR EH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR RH ACCIDENT AFFECTED AREAS				✓	1770 3540.00
10	1	BP-RES2 RESPRAY JOB ON REAR RH ACCIDENT AFFECTED AREAS	1.00	589.50		✓	589.50
11	2	T52159-47912 COVER, RR BUMPER T52155-47010 SUPPORT, RR BUMPER	1.00	151.20		✓	151.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		Amount Due
					Lubrication/Fluid		
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611. Tel no 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tan Li Kai (Chen Likai) 260 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681 Mobile: 90073103			
			Document No. 0					
			Document Date 11/04/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	0	21685	67/DS/SMV0775C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU80J060567		2ZR2H39377	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	3	T52575-47030 RETAINER, RR BUMPER <i>new</i>			1.00	62.70		✓ 62.70
13	4	S52161-0K040 CLIPS <i>new</i>			10.00	4.30		✓ 43.00
14	5	T52023-12240 REINFORCEMENT <i>new</i>			1.00	230.20		✓ 230.20
15	6	T52015-47080 ARM SUB-ASSY, RR <i>new</i>			1.00	186.30		✓ 186.30
16	7	T76891-47040 SPOILER, RR NO.1 <i>new</i>			1.00	899.70		✓ 899.70
17	8	T58307-47080 PANEL SUB-ASSY, BODY <i>new</i>			1.00	738.00		✓ 738.00
18	9	T61601-47111 PANEL SUB-ASSY, <i>new</i>			1.00	1023.30		✓ 1023.30
19	0	T67935-47010 C0 PLATE, BACK DOOR <i>new</i>			1.00	192.50		✓ 192.50
20	1	T67005-47460 PANEL SUB-ASSY, BACK <i>new</i>			1.00	1177.30		✓ 1177.30
21	2	T75310-47020 EMBLEM ASSY <i>new</i>			1.00	67.20		✓ 67.20
22	3	T75442-47080 PLATE, BACK DOOR <i>new</i>			1.00	67.20		✓ 67.20
23	4	T75441-47130 PLATE, LUGGAGE COMPT <i>new</i>			1.00	58.00		✓ 58.00
24	5	T81551-47262 LENS & BODY, RR <i>cracked</i>			1.00	730.90		✓ 730.90
25	6	TREVSE-47006 16 BACK SENSOR 070 WHITE PEARL <i>new</i>			1.00	101.05		✓ 101.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is a condition for insurance claim
- Any modification must be resurveyed and is subject to final approval from Insurance Company

For & on behalf of **Borneo Motors (Singapore) Pte Ltd**

Acknowledged by Repairer

Signature: _____

Date: _____

Adrian G
P/P 25/04/22
04 Days

Charge Summary		Total
Parts	6,318.05	15,351.20
Labour	8,670.00	
Sublet	363.18	
Lubrication/Fluid	0.00	
Others	0.00	
GST 7.00%		1,074.50
Less		0.00
Amount Due		16,425.80

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tan Li Kai (Chen Likai)		
			Document No. 39012648		200 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681		
			Document Date 09/05/2022		Mobile: 90073103		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	34833	21685	67/DS/SMV0775C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU80J060567		2ZR2H39377	60	Sam San Joi	21/03/2022 15.12		09/05/2022 13.09
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRIES SUNDRIES TP-DIRECT SETTLEMENT TP-SLD3959B ACC DATE:21/03/2022 DRIVE IN:21/03/2022 DATE-IN:26/04/2022 DATE SURVEY:26/04/2022 NO OF REPAIR DAYS: BY:ADRIAN(LKK)				30.00	
2	S	PSP PEK PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	0619			183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR	*			180.00	
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST	*			180.00	
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR	*			360.00	
6	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
7	B	BP-LAB2 REPLACE REAR EH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR RH ACCIDENT AFFECTED AREAS	*			1440.00	
8	B	BP-RES2 RESPRAY JOB ON REAR RH ACCIDENT AFFECTED AREAS				1770.00	
9	1	T52159-47912 COVER, RR BUMPER	1.00	589.50		589.50	
10	2	T52575-47030 RETAINER, RR BUMPER	1.00	62.70		62.70	
11	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.30		43.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details				
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Tan Li Kai (Chen Likai)				
			Document No. 39012648		260 Yio Chu Kang Road #04-04 Hundred Palms Residences Singapore 545681				
			Document Date 09/05/2022		Mobile: 90073103				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	ZVW40R	AWXEBW Q3	16/09/2020	SMV0775C	34833	21685	67/DS/SMV0775C		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDZS3EU80J060567		2ZR2H39377	60	Sam San Joi	21/03/2022 15.12		09/05/2022 13.09		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
12	4	T76891-47040	SPOILER, RR NO.1			1.00	899.70		899.70
13	5	T75310-47020	EMBLEM ASSY,			1.00	67.20		67.20
14	6	T75442-47080	PLATE, BACK DOOR			1.00	67.20		67.20
15	7	T81551-47262	LENS & BODY, RR			1.00	730.90		730.90
16	8	T62930-44010	DUCT ASSY, QUARTER			1.00	169.40		169.40
17	9	U81910-47010	REFLECTOR ASSY, <i>reboxed missing</i>			1.00	63.40		63.40
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		7,016.18			
				Labour		491.13			
				Sublet		0.00			
				Lubrication/Fluid					
				Others					
				2,693.00		GST 7.00%			
				3,960.00		Less			
				363.18		Amount Due			
				0.00		7,507.31			
				0.00					

Customer Copy