



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 20.03.2022
Emailed : 04.04.2022, 12pm
Date Survey : 23.03.2022

VEHICLE NO : SLS 7831 E
MODEL : MIT OUTLANDER 2.4
WIP : 21802

Material	:	\$	824.67
Labour	:	\$	960.00
Sub-Total	:	\$	1,784.67
	:	\$	-
Less Excess	:	\$	600.00
Total	:	\$	1,184.67
GST 7%	:	\$	82.93
Grand Total	:	\$	1,267.60
Finalise By/Date	:	LOI /	04/04/2022

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 23/03/2022	Cust No/Name /MR MUHAMMAD HAFIZ BIN JAMAL Reg No/Reg Date SLS7831E / 04/10/2017 Date In/Mileage 22/03/2022/ 69978 Chassis/Package JMYXTGF3WJZ000347 /# Engine No 4B12TP2745 Make/Model MIT/OUTLANDER 2.4 CVT AWD (E04) Colour/Trim D01 COSMIC BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	04/04/2022/ 12:33	BLK	260 / AiTing	21802			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 450.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 350.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 10.00
X EXC INSURANCE EXCESS								-600.00
X GARNISH,FR BUMPER SIDE					1.00	✓ 220.00	23.00	169.40
X FACE,FR BUMPER					1.00	✓ 851.00	23.00	655.27
Z TEXT AIG OD CLAIM DOA : 20.03.22 SURVEYOR STEVE-LKK 23.03.22 REPAIR 03 DAYS								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	824.67	Nett	1,184.67
Labour	950.00	7% GST on	82.93
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	1,267.60
Diagnostics Job	0.00		
Sundry/Others	-590.00		
Total(w/o GST)	1,184.67		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Prevois 223031E
Gates to use

APR 23 not out to Base
will be for
at Sub Don
by 6:00 get done

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21121-00
V.C.I. Version	B179
Vehicle Information	GF3W 2018MY

All DTCs

2022.03.28

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition				
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs					
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs					
	AUTO CRUISE	GAS_0E640000		Non-target System					
	4WS/Electric Power Steering	EPS_45880040		No DTCs					
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs					
	SRS-AIR BAG	ORC_81047302		No DTCs					
	Air Conditioner	AC_80080011		No DTCs					
	ETACS	ETACS_83040801		No DTCs					
	Meter	MTR_84084001		No DTCs					
	Steering Angle Sensor	GS_SAS_47000100		Non-target System					
	AWC	AWC_16080002		No DTCs					
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error					
	LIN	ETACS_83040801		Non-target System					
	Power Gate	ETG_92080000		Non-equipped System or Communication Error					
	KOS/IMMO/Keyless (IMMOBI & KOS)	KOS_8A880020		No DTCs					

All DTCs

2022.03.28

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
	EPB	EPB_4C080000		No DTCs		