

ASS. REC. BY:

REF:

A/G 22002672/Ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. 11/24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGZ 7409P Yr Regn: 11, 07Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios C.C. 1492Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 258832 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0531449305026922Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / 8/Rim / STD A/Rim orTyre Size: F: 205/50ZR16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 21/3/22 D.O.I. 30/3/2022

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/4 11pm @ 2800 Cash

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Tropical Tech Automobile Services

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #09-16,
Singapore 079120

Estimate bill : TT 07 / 22 / TP / WT

Registration No : SGZ7409P

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Make model : Toyota Vios

Mileage :

Date : 23 / 03 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SMH5829Y AND SGZ7409P ALONG UPPER BUKIT TIMAH ROAD ON 21 MARCH 2022 AT ABOUT 1835HRS.

1pc	Rear boot	681.20			\$	Bu	862.00	✓
1pc	Rear boot emblem	53.90			\$	mu	87.00	—
1pc	Rear boot 'Vios' designation	42.50			\$	mu	97.00	—
2pcs	Rear boot hinge		(Each \$78.00)		\$	nc	156.00	X
1pc	Rear boot lock	109.50			\$	nd	156.00	✓
1pc	Rear boot rubber	152.20			\$	Dis mu	189.00	508.00
2pcs	Rear tail lamp		(Each \$328.00)		\$	CM	656.00	—
1pc	Rear end panel	590			\$	By	724.00	—
1pc	Rear end panel top garnish	158.60			\$	nd	218.00	—
1pc	Rear bumper				\$	Bu	517.00	✓
2pcs	Rear bumper side bracket (Small)		n/s nd (Each \$52.00)		\$	d/s	104.00	4
2pcs	Rear bumper side bracket (Big)		n/s Bu (Each \$90.00)		\$	in	180.00	X
	Sub total :				\$		3,946.00	
	Less 25% discount :				\$		986.50	
	A total :				\$		2,959.50	

Special net items :

1pc	Rear license plate	\$	su	25.00	X
1set	Rear bumper parktronic sensor kit	\$	su	280.00	X
	B total :	\$		305.00	

Total amount for Page : 1

\$ 3,264.50

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Not withstanding
11 Pm @ 2800h
Mercury After Rain
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte Ltd**
78, Shenton Way, #09-16,
Singapore 079120

Estimate bill : TT 07 / 22 / TP / WT

Registration No : SGZ7409P

Attn : **Motor Claims Department**
Tel : 6419 3000
Fax : 6225 6772

Make model : Toyota Vios

Mileage :

Date :

23 / 03 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SMH5829Y AND
SGZ7409P ALONG UPPER BUKIT TIMAH ROAD ON 21 MARCH 2022 AT ABOUT 1835HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot emblem, rear boot 'Toyota Vios'
designation, rear boot lock, rear tail lamp, rear end panel top garnish, rear bumper,
rear bumper parktronic sensor kit, rear bumper side bracket (Small), rear bumper
side bracket (Big).

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten /
align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear end panel, rear bumper,
rear bumper parktronic sensor kit.

Balance amount brought from Page 1 :

\$	700.00	609
\$	100.00	501
\$	80.00	201
\$	200.00	601
\$	700.00	60d
\$	3,264.50	
\$	5,044.50	

Grand final amount :

Tropical Tech Automobile Services

(Authorised Signature)

William Tan

