

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 23 Mar 2022

ASSESSMENT FOR REPAIR: YAMAHA GDR155A AEROX - FBP7162L

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Wheel axle	\$65.00
1 pc	Left fork assy	\$395.00
1 pc	Steering stem	\$220.00
2 pcs	Steering stem bearings @ \$45.00	\$90.00
1 pc	Handle bar	\$145.00
1 pc	IU bracket	\$35.00
1 pc	Brake lever left	\$48.00
1 pc	Balancer left	\$35.00
1 pc	Left handle grip	\$29.00
1 pc	Radiator cover	\$85.00
1 pc	Left body cover emblem	\$35.00
1 pc	Left body cover	\$125.00
1 pc	Left floorstep under	\$95.00
1 pc	Left floor step	\$120.00
1 pc	Airbox assy	\$145.00
1 pc	Left engine cover	\$115.00
1 pc	Exhaust heat shield	\$95.00
1 pc	Exhaust assembly	\$399.00
		\$2,276.00
	Less discount 10%	\$227.60
		\$2,048.40
	<u>Special nett items</u>	
1 pc	ERP IU	\$157.00
1 pc	Front sport rim	\$350.00
1)	Towing charges	\$100.00
	Replace, realign and adjust above damaged parts, check wiring and	
2)	lighting system	\$700.00
	To remove, replace and balance	
3)	front wheel rim	\$120.00
	To knock, straighten chassis & body	
4)	balancing	\$380.00

5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00
	Total Estimate	<u><u>\$4,035.40</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd