



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22002686/Vty3e2 Date: 11/04/2022 Code: SMR		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SHB 734K	Veh. Inspected		FBD 6831J
Policy No.			Coverage (\$)		0.00
Claim No.		TAX/02/22/2054	Excess (\$)		0.00
Assign From		HUA YEN	Assign Date		23/03/2022
2. Vehicle Particulars & Condition					
Make & Model		YAMAHA FZ6S	c.c		600
Engine No.		HIDDEN	Year of Reg.		2009
Chassis No.		JYARJ149000007747	Colour		BLACK
Odometer		-	Steering		IN ORDER
Brakes		IN ORDER	Modification		STANDARD ALLOY RIM
General		FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	180/55ZR17	BRIDGESTONE	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	180/55ZR17	BRIDGESTONE	5 mm	
	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5. General Information					
	Accident Date	21/02/2022	Inspect Date / Time 23/03/2022 (04:00 PM)		
	Survey held at	CANDYMOTOR WORKSHOP PTE LTD 25 KAKI BUKIT ROAD 4 #01-69/70 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/SMR22002686/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.