

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : 21/22/22/VC05/025586 Date: 17<sup>th</sup> May 2022

Our Ref : CS/LPC22002692/Gqy3e2

## M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YN 3261Z ACCIDENT ON 17/03/2021

Instruction was received to inspect the vehicle Reg. No. YN 3261Z. The inspection was conducted on 23/03/2022 at the premises of M/s Kan Fook Sing Motor Workshop, 61 Defu Lane 12, Singapore 539147.

The following vehicle information was recorded:

Registration Number : YN 3261Z

Make/Model : Mitsubishi FM65FM1RDEA

Year of Registration : 2012 Body Colour : White

Chassis Number : FM65FMA00218

Engine Capacity : 7545 cc Speedometer Reading : Nil

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is \$\$28,569.50 (Sin Dollars: Twenty-Eight Thousand Five Hundred Sixty-Nine and Fifty cents only.) (Include check items \$\$17,726.50Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a)	If the vehicle to be "Total Loss"

Market Value

S\$ 12,000.00(est)

Less: LTA Reimbursement Value (RV)

(S\$ 543.00)

11,457.00 S\$

Less: Excess

2,000.00) (<u>S\$</u>

Nett Liability S\$ 9,457.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

28,569.50

(Include check items S\$17,726.50Nett)

Less:Excess (S\$ 2,000.00)

Nett Liability

S\$ 26,569.50

(a) - (b) =

(S) 17,112.50

The amount of estimated saving of S\$17,112.50 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

XING GUO QIANG M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.