



簡福星摩王廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

DATE : 25-03-2022

VEHICLE NO. : YN3261Z
ACCIDENT DATE : 17-03-2022 16:45
THIRD PARTY REF. : XD7565K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE YN3261Z MITSUBISHI FM65FM1RDEA

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT WINDSCREEN RUBBER ?	280.00
2	1	FRONT WINDSCREEN PILLAR RH ?	900.00
3	1	FRONT WINDSCREEN PILLAR CENTRE RH ?	550.00
4	1	FRONT WINDSCREEN PILLAR INNER RH ?	400.00
5	1	FRONT BONNET / bnc	2000.00
6	2	FRONT BONNET LOCK @\$135.00 ?	270.00
7	1	FRONT BONNET FUSO EMBLEM / MLC	160.00
8	1	FRONT GRILLE TOP / SQA	260.00
9	1	FRONT GRILLE LOWER / MLC	380.00
10	1	FRONT GRILLE EMBLEM / MLC	160.00
11	1	FRONT CORNER PANEL RH / MLC	650.00
12	1	FRONT CORNER PANEL BRACKET RH ?	155.00
13	1	FRONT HEADLAMP RH / D.S	750.00
14	1	FRONT HEADLAMP BRACKET RH ?	450.00
15	2	FRONT HEADLAMP RIM@\$160.00 ?	320.00
16	1	FRONT BUMPER / BT	850.00
17	2	FRONT BUMPER BRACKET @\$125.00 ?	250.00
18	1	FRONT BUMPER SIDE GARNISH RH ?	120.00
19	1	FRONT BUMPER AIR DUCT RH ?	100.00
20	2	FRONT BUMPER COVER@\$180.00 ?	360.00
21	1	FRONT STEP GARNISH RH / D.S	280.00
22	1	FRONT STEP RH / D.S	220.00
23	1	FRONT STEP REFLECTOR RH / MLC	180.00
24	1	FRONT STEP PANEL ?	320.00
25	1	FRONT DOOR RH / BT	1880.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : YN3261Z
ACCIDENT DATE : 17-03-2022 16:45
THIRD PARTY REF. : XD7565K

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
26	1	FRONT DOOR LAMP RH	160.00
27	1	FRONT DOOR RUBBER RH	160.00
28	1	FRONT DOOR LOCK RH	350.00
29	1	FRONT DOOR HINGE TOP RH	125.00
30	1	FRONT DOOR HINGE LOWER RH	125.00
31	1	FRONT DOOR CHECKER RH	100.00
32	1	FRONT BODY FAME RUBBER RH	220.00
33	1	FRONT WHEEL ARCH PANEL RH	450.00
34	1	FRONT WHEEL ARCH GARNISH RH	300.00
35	1	FRONT WHEEL ARCH GARNISH RUBBER RH	160.00
36	1	FRONT CROSS MEMBER TOP	850.00
37	1	FRONT CROSS MEMBER LOWER	800.00
38	1	STEERING BOX ASSY	2850.00
39	1	FRONT CHASSIS ROD (RH)	850.00
40	1	FRONT CHASSIS ROD BRACKET (RH)	300.00
41	2	FRONT HEAD MOUNTING @\$400.00	800.00
42	2	FRONT HEAD MOUTNING BRACKET @\$150.00	300.00
43	1	DASHBOARD ASSY	1250.00
44	1	DASHBOARD REINFORCEMENT	850.00
			23,245.00
ADD 10 %			2,324.50
TOTAL (A)			25,569.50

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE	30.00
2	1	ERP STICKER	10.00
TOTAL (C)			40.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	100.00
---	---	------------------------	--------

30



簡福星嘜王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : YN3261Z
ACCIDENT DATE : 17-03-2022 16:45
THIRD PARTY REF. : XD7565K

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
2	1	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	120.00 ?
3	1	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	80.00 60
4	1	TO REMOVE & REFIT FRONT CABIN HEAD	450.00 ?
5	1	REMOVE & REFIX DASHBOARD ASSY	300.00 ?
6	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	2200.00 800
7	1	SPRAYPAINTING CHARGES	1500.00 1200
TOTAL (D)			4,750.00
ESTIMATE TOTAL			30,359.50

6 Days.
Camp repair
After repair photos.
One Qiang

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: