



Accident Reference & Bus No: E/1175/2022 SBS8432K With SGR828B

Activated date: 23/3/2022

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Thevan
Company Name: LKK
Date Surveyed: 25/3/22 1630
Thevan@lkkh1auto.com
Require 82235769
Resurvey 1 Date:
Resurvey 2 Date:

Repair and Respray paint
- Front RHS Lamp cover
- RHS below bc glass panel
- RHS wheel arc trim

Final Endorsement by Surveyor:

Estimate for

- ☐ Parts cost: \$ _____
☐ Contractor Labour cost: \$ 600 ✓
☐ Workshop Labour cost: \$ 184 xx
☐ Advertisement Cost: \$ 0
☐ Repair period: 2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- ☐ Tow Cost: \$ 0
☐ Loss of use: \$ _____
☐ Overheads: \$ _____