

Mr: Thuan

CS/E9122002673/uty3

ASSIGNMENT

Date:

Veh No: SBS84324

Yr Rog: 9/12/08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Scanla huBLLX2

CC: 8798

Colour: Multicolour

NC: Insured / Std / NI / NA

Sp. Reading: 86520

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YS24x20001862412

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SIR / STD AIR / or

Tyre Size: F: 275/70 R22.5

R: 275/70 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 13/3/22

D.O.I.

Survey held at SBS head depot

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

TP / ES / OD / RES / EVA / INV / MV

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Ref:

Excess:

had commenced its
the time of inspection.

N/S	O/S

Consistent? : Yes or No

Consistent? : Yes or No

2 days Res.: Yes or No

% 3 Val.: Yes or No

24 HRS

Person Contacted:

Vehicle: IN / OUT

Person / Instruction

☐ : Prelim. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : V/A & Eng (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fuel

Driver

Tools

Other

Total


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	653M
Vehicle Details	
Vehicle No.:	SBS8432K
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2022
Vehicle Make:	SCANIA
Vehicle Model:	KUB4X2 8.9 AUTO ABS TURBO 2WD
Primary Colour:	Multicolor
Manufacturing Year:	2008
Engine No.:	6337206
Chassis No.:	YS2K4X20001862412
Maximum Power Output:	-
Open Market Value:	\$309,418.00
Original Registration Date:	09 Dec 2008
First Registration Date:	09 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$15,471.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 29 Mar 2022

OK



Accident Reference & Bus No: **E/1175/2022 SBS8432K With SGR828B**

Activated date: **23/3/2022**

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Thevan
 Company Name: LKK
 Date Surveyed: 25/3/22 1630
 Require Thevan@lkkhifuto.com
 Resurvey 1 Date: 82235769
 Resurvey 2 Date:

Repair and Respray paint
 - Front RHS Lamp cover
 - RHS below bc glass panel
 - RHS wheel arc trim

Final Endorsement by Surveyor:

Estimate for

- ☐ Parts cost: \$ _____
☐ Contractor Labour cost: \$ 600
☐ Workshop Labour cost: \$ 184
☐ Advertisement Cost: \$ 0
☐ Repair period: 2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- ☐ Tow Cost: \$ 0
☐ Loss of use: \$ _____
☐ Overheads: \$ _____