



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002698/Aty3n2	
			Date: 31/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 7799A	Veh. Inspected	SJC 7332L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200977/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	23/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416048744	Colour	WHITE	
Odometer	191845 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	FIRENZA	6 mm	
L/H Front Tyre	195/60 R15	FIRENZA	6 mm	
R/H Rear Tyre	195/60 R15	FIRENZA	6 mm	
L/H Rear Tyre	195/60 R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2022	Inspection Date	24/03/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	