

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 22/03/2022

Estimated repair cost for vehicle no: SJC7332L TOYOTA COROLLA AXIO 1.5X A

CHASSIS: NZE1416048744

23/03/2022

TP Somp
Denise.

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Distorted</i>	\$941.30	<u>\$941.30</u> <i>542</i>
2	1	FRONT BUMPER REINFORCEMENT <i>see in</i>	\$282.25	\$282.25 <i>+</i>
3	1	FRONT BUMPOER SPONGE <i>crushed</i>	\$212.50	<u>\$212.50</u> <i>185</i>
4	1	FRONT BUMPER SIDE RETAINER <i>Rit Danged</i>	\$68.70	\$68.70 <i>55</i>
5	1	FRONT BUMPER FOG LAMP COVER <i>2 piece</i>	\$179.30	\$179.30 <i>+</i>
6	1	FRONT BUMPER UNDER COVER	\$311.20	\$311.20 <i>+</i>
7	1	FRONT GRILLE <i>crushed</i>	\$499.30	<u>\$499.30</u> <i>375</i>
8	1	FRONT GRILLE LOGO <i>na</i>	\$104.50	<u>\$104.50</u> <i>55</i>
9	1	FRONT SUPPORT PANEL <i>Ry</i>	\$845.60	\$845.60 <i>x</i>
10	1	RH FRONT FENDER <i>Buckled</i>	\$623.40	\$623.40 <i>-</i>
11	1	RH FRONT FENDER INNER COWLING <i>see in</i>	\$187.60	\$187.60 <i>+</i>
12	1	WIPER WASHES TANK <i>see in crushed</i>	\$218.10	<u>\$218.10</u> <i>121</i>

13 1 Handling RH *Crushed*

809.40 ✓

TOTAL :	<u>\$4,473.75</u>
LESS 25 %	<u>\$1,118.44</u>
SUB-TOTAL :	<u>\$3,355.31</u>

770580

2096.855

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPR CLIPS <i>new</i>	\$80.00	\$80.00 <i>30</i>
2	1	FRONT GRILLE CLIPS <i>new</i>	\$40.00	\$40.00 <i>30</i>
3	1	RH FRONT FENDER INNER COWLING CLIPS <i>3 new</i>	\$60.00	\$60.00 <i>x</i>
4	1	FRONT NUMBER PLATE WITH CASING <i>new</i>	\$60.00	\$60.00 <i>+</i>

60

TOTAL: \$240.00

TOTAL PARTS: \$3,595.31

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS

Q60

\$800.00 *500*
\$800.00 *400*
\$60.00 *30*
\$200.00 *30*

Subtotal :- \$1,860.00

Adnan Lj
L/S 24/03/22 **Total:-** \$5,455.31

04 Days

total: 3106.85
L/S: 2.5K
2.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: