

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002702/UEA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800103707
Claimant Vehicle No :	SNE209Z	Insured Vehicle No :	SME304T
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	7982462241SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE209Z		
Make & Model:	BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)	Engine No:	34099691B37C15A
Reg. Date:	31/10/2016 (Man. Year: 2016)	Chassis No:	WBA2E320305B45481
Colour:	Grey	Odometer:	92536 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,681.48	2,873.33	5,808.15	66.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,410.00	1,300.00	47.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,391.48	4,283.33	7,108.15	62.40
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	11,391.48	3,400.00	7,991.48	70.15
+ GST 7.00/7.00% (S\$)	797.40	238.00	559.40	70.15
Nett Amount (S\$)	12,188.88	3,638.00	8,550.88	70.15
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,175.00		

INSPECTION

Date of Assignment:	24/03/2022		
Date Inspected:	24/03/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	1,025.50 FL	*- FL
2	1		*REAR BUMPER CLIP	Not Necessary	19.20 FL	*- FL
3	1		*N/S REAR BUMPER SIDE GUIDE	Not Necessary	59.50 FL	*- FL
4	1		*N/S REAR FENDER	Repair	1,494.35 FL	*- FL
5	1		*N/S REAR FENDER INNER COWLING	Not Necessary	380.00 FL	*- FL
6	1		*N/S REAR FENDER QUARTER GLASS MOULDING	Not Necessary	299.40 FL	*- FL
7	1		*N/S REAR DOOR	Badly Dented	1,281.70 FL	*1,281.70 FL
8	1		*N/S REAR DOOR END COVER	Necessary	112.00 FL	*112.00 FL
9	1		*N/S REAR DOOR OUTER MOULDING (CHROME)	Not Necessary	186.00 FL	*- FL
10	1		*N/S REAR DOOR WINDOW GLASS	Not Necessary	396.00 FL	*- FL
11	1		*N/S REAR DOOR WEATHERSTRIP	Necessary	220.00 FL	*220.00 FL
12	1		*N/S FRONT DOOR	Repair	1,538.00 FL	*- FL
13	1		*N/S ROCKER PANEL GARNISH	Cut	690.00 FL	*690.00 FL
14	1		*N/S REAR WHEEL RIM	Cut	1,250.00 FS	*800.00 FS
15	1		*N/S REAR TYRE	Serviceable	500.00 FS	*- FS
					Sub Total (\$\$)	9,451.65 3,103.70
					- List Item Discount on L Items 10.00/10.00% (\$\$)	770.17 230.37
					Total Parts (\$\$)	8,681.48 2,873.33

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	240.00	60.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	120.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	30.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	800.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	500.00
Gross Labour Cost (S\$)			2,710.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >