



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0213/2022/NK
DATE : 22-Mar-22
WIP : 16402

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LOW YANN NI, JENNY (LUO YANNI, JENNY)
ADDRESS : 156 HAIG ROAD
#06-06
SINGAPORE 438793
TELEPHONE : 96236085
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900166794-01
VEHICLE NO : **SCH 6088 E**
MODEL CODE : AUDI A5 SB 12.0 TFS
MODEL YEAR : 27/9/2019
ENGINE NO : CVK087656
CHASSIS NO : WAUZZZF53KA076164
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Mar-22
PLACE OF ACCIDENT : 152 HAIG RD,S 438791 HAIG COURT CAR PARK EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCH 6088 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	X-
2	TO RENEW LHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER.	S/N \$ 300.00	✓ ✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$ 400.00	✓ ✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	S/N \$ 200.00 150	✓
5	TO DISLUDGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$ 1,400.00	✓ ✓
6	TO REMOVE AND AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLUDGE ROOF LINER AND DISENGAGE CURTAIN AIRBAGS ETC	S/N \$ 1,400.00	✓ ✓
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 280	✓
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REMOVE AND RENEW LHS SILL PANEL TRIM AND LHS REAR DOOR. REORGANISE CRASH MANAGERMENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 3500	✓
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR HANDLE, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANEL FITTING.	\$ 7,000.00	4.5 x 550 = 2475 ✓
10	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGMENT TEST	S/N \$ 280.00	✓ ✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 19,132.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCH 6088 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	SECTIONAL PART LH <i>Dented</i>	1	\$ 4,076.00	✓ 3260.80
2	REAR SIDE WINDOW LH <i>slur</i>	1	\$ 798.00	✓ 638
3	SIDE MEMBER TRIM LH <i>Repair</i>	1	\$ 872.00	* 108.80
4	ATTACHMENTS PARTS <i>slur slur</i>	1	\$ 136.00	✓ 176.80
5	ADHESIVE TAPE <i>slur</i>	1	\$ 221.00	✓
6	WHEEL HOUSING LINERS LH <i>slur</i>	1	\$ 299.00	*
7	WHEEL HOUSING LINERS ATTACHMENTS PARTS LH <i>slur</i>	1	\$ 176.00	*
8	REAR BUMPER GUIDE SECTION LH <i>slur</i>	1	\$ 49.00	*
9	REAR DOOR LH <i>Dented</i>	1	\$ 3,977.00	✓ 3181.60
10	REAR DOOR OUTER SEAL LH <i>slur</i>	1	\$ 247.00	✓ 197.20
11	BONDING AGENT ?	1	\$ 51.00	? X
12	CLEANING SOLUTION ?	1	\$ 74.00	? X
13	APPLICATOR ?	1	\$ 8.00	? X
14	REAR DOOR CATCH ?	1	TBC	? X
15	REAR ALUMINIUM RIM LH <i>cut</i>	1	\$ 1,889.00	✓ 1511.20
16	RUBBER VALVE <i>slur</i>	1	\$ 15.00	*
17	PRIMER <i>slur</i>	1	\$ 22.00	✓ 17.36
18	STONE CHIPS <i>slur</i>	S/N	\$ 180.00	✓ 180
19	METAL FILLER POWDER <i>slur</i>	1	\$ 280.00	✓ 280
20	ACYRLIC SEALANT <i>slur</i>	2	\$ 180.00	✓ 180
SUB TOTAL SPARE PARTS		:	\$ 13,550.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCH 6088 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	CAVITY WAX <i>3 sec</i>	S/N	\$ 140.00	✓ 140
42	1/4 GLASS SEALANT	S/N	\$ 100.00	✓ 100
43	SUNDRIES ?	1	\$ 500.00	? 13.04
TOTAL SPARE PARTS		:	\$ 14,290.00	
TOTAL LABOUR CHARGES		:	\$ 19,132.00	
GRAND TOTAL		:	\$ 33,422.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan Ling
SURVEYED DATE : 23/03/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 13 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT