



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0212/2022/NK
DATE : 22-Mar-22
WIP : 16251

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHAN KIM LENG
ADDRESS : BLK 757, PASIR RIS STREET 71
#10-168
SINGAPORE 510757
TELEPHONE : HP +65 96186277
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100413971-06
VEHICLE NO : **SGM 1800 A**
MODEL CODE : AUDI A4 1.8 FSI MU
MODEL YEAR : 29/5/2015
ENGINE NO : CJE 100729
CHASSIS NO : WAUZZZ8K2FA117375
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Mar-22
PLACE OF ACCIDENT : TPE TURNING INTO PUNGGOL



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGM 1800 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY.	S/N \$ 360.00	?
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND RFGAS	S/N \$ 1,400.00	x.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 5,600.00	1500
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER AND RHS UPPER A-PILLAR.	\$ 5,000.00	1650.
6	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		: \$ <u>13,444.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defend</i>	1	\$ 2,725.00	✓
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 271.00	X
3	FRONT BUMPER CLOSING ELEMENTS <i>Xben</i>	1	\$ 254.00	X
4	FRONT BUMPER GRILLE LOWER CENTRE <i>Xben</i>	1	\$ 151.00	X
5	FRONT BUMPER CLOSING ELEMENTS UPPER CENTRE <i>Neu</i>	1	\$ 271.00	X
6	FRONT BUMPER SUPPORT ELEMENT UPPER <i>Xben</i>	1	\$ 66.00	X
7	RADIATOR GRILLE <i>Conchd</i>	1	\$ 1,205.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>? Xben</i>	2	\$ 302.00	X
9	FRONT WHEEL SPOILER FRONT LH / RH	2	\$ 114.00	+
10	FRONT REINFORCEMENT BEAM <i>?</i>	1	\$ 985.00	?
11	FRONT BUMPER FOAM FILLER <i>Conchd</i>	1	\$ 139.00	✓
12	FRONT BUMPER SUPPORT <i>?</i>	2	\$ 29.00	?
13	FRONT BUMPER GUIDE SECTION LH / RH <i>Xben</i>	2	\$ 82.00	X
14	FRONT BUMPER TOP COVER <i>Defend</i>	1	\$ 143.00	✓
15	FRONT BUMPER BRACKET LH <i>?</i>	1	\$ 255.00	?
16	STICKER SIGNAGE " CAUTION HIGH VOLTAGE" <i>Neu</i>	1	\$ 16.00	✓
17	STICKER SIGNAGE " FOR AIR CONDITIONER" <i>Neu</i>	1	\$ 34.00	✓
18	SIGNAL HORN HIGH TONE LH <i>?</i>	1	\$ 214.00	?
19	SPRING SHACKLE HIGH TONE LH <i>?</i>	1	\$ 28.00	?
20	FRONT FENDER LH / RH <i>RH Defend</i>	2	\$ 2,222.00	1111
SUB TOTAL SPARE PARTS			\$ 9,506.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENTS	1	\$ 60.00	+
22	FRONT FENDER BRACE LOWER LH / RH	2	\$ 264.00	+
23	FRONT FENDER BRACKET FRONT LH / RH	2	\$ 118.00	+
24	POP RIVET	8	\$ 31.00	✓
25	FRONT WHEEL HOUSING LINERS LH / RH	2	\$ 520.00	+
26	STONE CHIP GUARD LH	1	\$ 82.00	+
27	ADHESIVE TAPE	1	\$ 59.00	+
28	STONE CHIP GUARD RH	1	\$ 82.00	+
29	ADHESIVE TAPE	1	\$ 59.00	+
30	BONNET	1	\$ 3,414.00	✓
31	BONNET PROTECTIVE FILM FRONT	1	\$ 51.00	+
32	BONNET ATTACHMENTS PARTS	1	\$ 176.00	+
33	BONNET LID HINGE LH / RH	2	\$ 166.00	+
34	BONNET CATCH HOOK	1	\$ 155.00	+
35	BONNET LID LOCK w MICRO SWITCH	1	\$ 228.00	+
36	BONNET LID LOCK CABLE FRONT	1	\$ 55.00	+
37	BONNET EDGE PROTECTION FRONT	1	\$ 31.00	✓
38	BONNET LOCK COVER	1	\$ 26.00	+
39	HEADLIGHT MOUNTING LH/ RH	2	\$ 264.00	+
40	HEADLIGHT BRACKET LH / RH	2	\$ 236.00	+
SUB TOTAL SPARE PARTS			\$ 6,077.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT DISCHARGE LAMP LH / RH <i>kit could</i>	2	\$ 4,984.00 2492	
42	HEADLIGHT LIFT CYLINDER LH / RH <i>3 new</i>	2	\$ 462.00	x
43	HEADLIGHT LIFT CYLINDER HOSE ROLLERS	1	\$ 204.00	x
44	AIRCON CONDENSER <i>3 new</i>	1	\$ 816.00	x
45	AIRCON CONDENSER BRACKET	1	\$ 21.00	x
46	CHARGE AIR COOLER <i>new</i>	1	\$ 628.00	x
47	RADIATOR <i>new</i>	1	\$ 1,442.90	x
48	RADIATOR LOWER SUPPORT <i>new</i>	1	\$ 43.00	x
49	AIR GUIDE LH / RH	2	\$ 84.00	x
50	READY MIX COOLANT 1.0 L	6	\$ 282.00	x
51	INTAKE MANIFOLD FRONT	1	\$ 107.00	x
52	BELLOWS RESONATOR <i>new</i>	1	\$ 119.00	x
53	COVER FOR PLENUM CHAMBER	1	\$ 83.00	x
54	WATER DEFLECTOR STRIP RH	1	\$ 75.00	x
55	FRONT NO PLATE <i>parted</i>	S/N	\$ 60.00	✓
56	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS			: \$ 25,393.90	
TOTAL LABOUR CHARGES			: \$ 13,444.00	
GRAND TOTAL			: \$ 38,837.90	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lij
SURVEYED DATE : 23/08/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT