



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGM 1800 A

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|--------------------------|----------------------------|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY. | S/N \$ 360.00 | ? ✓ |
| 2 | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N \$ 700.00 | 250 + 250 ✓ S/S |
| 3 | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS | S/N \$ 1,400.00 | x <u>480</u> ✓ S/S |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | \$ 5,600.00 | 1500 ✓ |
| 5 | TO RESPRAY FRONT BUMPER, BONNET, <u>HINGES</u> , BOTH ^{RH} FRONT FENDER AND RHS UPPER A-PILLAR. _{only} | \$ 5,000.00 | 1650 + 160 ✓ |
| 6 | TO CARRY OUT PRE / POST DIAGNOSTIC CHECK. | S/N \$ 384.00 | 182 ✓ |
| TOTAL LABOUR CHARGES | | : \$ 13,444.00 | |

Adrian Lj
 S/S

Add 1 more day for
 the replacement of
 condenser. S/S

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

| S/N | PARTS DESCRIPTION | QTY | DAMAGED PARTS & PRICES | |
|------------------------------|--|-----|------------------------|------------------------------|
| | | | S/NETT | REMARKS |
| 1 | FRONT BUMPER <i>Repaired</i> | 1 | S | 2,725.00 ✓ 2180 |
| 2 | FRONT BUMPER FIXING PARTS <i>Not in</i> | 1 | S | 271.00 x |
| 3 | FRONT BUMPER CLOSING ELEMENTS <i>Not in</i> | 1 | S | 254.00 ✓ |
| 4 | FRONT BUMPER GRILLE LOWER CENTRE <i>Not in</i> | 1 | S | 151.00 x |
| 5 | FRONT BUMPER CLOSING ELEMENTS UPPER CENTRE <i>Not in</i> | 1 | S | 271.00 ✓ 173.60 <i>ll.s.</i> |
| 6 | FRONT BUMPER SUPPORT ELEMENT UPPER <i>Not in</i> | 1 | S | 66.00 ✓ |
| 7 | RADIATOR GRILLE <i>Crushed</i> | 1 | S | 1,205.00 ✓ 964 |
| 8 | FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>Not in</i> | 2 | S | 302.00 ✓ |
| 9 | FRONT WHEEL SPOILER FRONT LH / RH | 2 | S | 114.00 ✓ |
| 10 | FRONT REINFORCEMENT BEAM <i>Dented.</i> | 1 | S | 985.00 ✓ 787.60 <i>ll.s.</i> |
| 11 | FRONT BUMPER FOAM FILLER <i>Crushed</i> | 1 | S | 139.00 ✓ 110.80 |
| 12 | FRONT BUMPER SUPPORT ? nn | 2 | S | 29.00 ✓ |
| 13 | FRONT BUMPER GUIDE SECTION LH / RH <i>Not in</i> | 2 | S | 82.00 x |
| 14 | FRONT BUMPER TOP COVER <i>Dented</i> | 1 | S | 143.00 ✓ 114 |
| 15 | FRONT BUMPER BRACKET LH ? nn | 1 | S | 255.00 ✓ |
| 16 | STICKER SIGNAGE " CAUTION HIGH VOLTAGE" <i>Not in</i> | 1 | S | 16.00 ✓ 12.40 |
| 17 | STICKER SIGNAGE " FOR AIR CONDITIONER" <i>Not in</i> | 1 | S | 34.00 ✓ 26.96 |
| 18 | SIGNAL HORN HIGH TONE LH ? nn | 1 | S | 214.00 ✓ |
| 19 | SPRING SHACKLE HIGH TONE LH ? nn | 1 | S | 28.00 ✓ |
| 20 | FRONT FENDER LH / RH <i>RH Dented</i> nn | 2 | S | 2,222.00 <i>ll.s.</i> x |
| SUB TOTAL SPARE PARTS | | | : | \$ 9,506.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

| | | | | | DAMAGED PARTS & PRICES | |
|------------------------------|------------------------------------|-----|--------|--------------------|------------------------|-----------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS | | |
| 21 | FRONT FENDER ATTACHMENTS | 1 | S | 50.00 | ✓ | |
| 22 | FRONT FENDER BRACE LOWER LH / RH | 2 | S | 264.00 | ✓ | |
| 23 | FRONT FENDER BRACKET FRONT LH / RH | 2 | S | 118.00 | ✓ | |
| 24 | POP RIVET | 8 | S | 31.00 | ✓ | 24.32 |
| 25 | FRONT WHEEL HOUSING LINERS LH / RH | 2 | S | 520.00 | ✗ | |
| 26 | STONE CHIP GUARD LH | 1 | S | 82.00 | ✓ | |
| 27 | ADHESIVE TAPE | 1 | S | 59.00 | ✓ | |
| 28 | STONE CHIP GUARD RH | 1 | S | 82.00 | ✓ | |
| 29 | ADHESIVE TAPE | 1 | S | 59.00 | ✓ | |
| 30 | BONNET | 1 | S | 3,414.00 | ✓ | 2731.20 |
| 31 | BONNET PROTECTIVE FILM FRONT | 1 | S | 51.00 | ✓ | |
| 32 | BONNET ATTACHMENTS PARTS | 1 | S | 175.00 | ✓ | |
| 33 | BONNET LID HINGE LH / RH | 2 | S | 166.00 | ✓ | 131.68 |
| 34 | BONNET CATCH HOOK | 1 | S | 155.00 | ✓ | |
| 35 | BONNET LID LOCK w MICRO SWITCH | 1 | S | 228.00 | ✓ | |
| 36 | BONNET LID LOCK CABLE FRONT | 1 | S | 55.00 | ✓ | |
| 37 | BONNET EDGE PROTECTION FRONT | 1 | S | 31.00 | ✓ | 24.72 |
| 38 | BONNET LOCK COVER | 1 | S | 26.00 | ✓ | |
| 39 | HEADLIGHT MOUNTING LH / RH | 2 | S | 264.00 | ✓ | 105.20 |
| 40 | HEADLIGHT BRACKET LH / RH | 2 | S | 236.00 | ✓ | 118 |
| SUB TOTAL SPARE PARTS | | | : | \$ 6,077.00 | | 94 |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

| | | | DAMAGED PARTS & PRICES | |
|-----------------------------|--|-----|------------------------|--|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 41 | HEADLIGHT DISCHARGE LAMP LH/RH <i>RH covered</i> | 2 | \$ 4,984.00 | 2492 4984.00 <i>3987.20</i> |
| 42 | HEADLIGHT LIFT CYLINDER LH / RH <i>2 me m</i> | 2 | \$ 462.00 | + |
| 43 | HEADLIGHT LIFT CYLINDER HOSE ROLLERS | 1 | \$ 204.00 | + |
| 44 | AIRCON CONDENSER <i>2 FAULTY Dented</i> | 1 | \$ 816.00 | <i>652.80</i> |
| 45 | AIRCON CONDENSER BRACKET <i>me m</i> | 1 | \$ 21.00 | - |
| 46 | CHARGE AIR COOLER <i>me m</i> | 1 | \$ 628.00 | + |
| 47 | RADIATOR <i>me m</i> | 1 | \$ 1,442.90 | + |
| 48 | RADIATOR LOWER SUPPORT <i>me m</i> | 1 | \$ 43.00 | + |
| 49 | AIR GUIDELINE LH/RH <i>Dented LH</i> | 2 | \$ 84.00 | <i>42</i> |
| 50 | READY MIX COOLANT 1.0 L | 6 | \$ 282.00 | + |
| 51 | INTAKE MANIFOLD FRONT | 1 | \$ 107.00 | + |
| 52 | BELLOWS RESONATOR <i>me m</i> | 1 | \$ 119.00 | + |
| 53 | COVER FOR PLENUM CHAMBER | 1 | \$ 83.00 | + |
| 54 | WATER DEFLECTOR STRIP RH | 1 | \$ 75.00 | + |
| 55 | FRONT NO PLATE <i>dented</i> | S/N | \$ 60.00 | <i>60</i> |
| 56 | SUNDRIES <i>nec</i> | 5 | \$ 400.00 | <i>68.64</i> |
| TOTAL SPARE PARTS | | : | \$ 25,393.90 | |
| TOTAL LABOUR CHARGES | | : | \$ 13,444.00 | |
| GRAND TOTAL | | : | \$ 38,837.90 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.