



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0212/2022/NK
DATE : 22-Mar-22
WIP : 16251

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Dear Adrian,
5 days ok

OWNER'S NAME : MR CHAN KIM LENG
ADDRESS : BLK 757, PASIR RIS STREET 71
#10-168
SINGAPORE 510757
TELEPHONE : HP +65 96186277
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100413971-06
VEHICLE NO : SGM 1800 A
MODEL CODE : AUDI A4 1.8 FSI MU
MODEL YEAR : 29/5/2015
ENGINE NO : CJE 100729
CHASSIS NO : WAUZZZ8K2FA117375
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Mar-22
PLACE OF ACCIDENT : TPE TURNING INTO PUNGGOL

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGM 1800 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$	1,400.00	\$	480.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$	1,500.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER AND RHS UPPER A-PILLAR.	\$	5,000.00	\$	1,810.00
6	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 13,444.00	\$	4,842.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY			S/NETT	REMARKS
1	FRONT BUMPER	1	\$	2,725.00	\$	2,180.00
2	FRONT BUMPER FIXING PARTS	1	\$	271.00		
3	FRONT BUMPER CLOSING ELEMENTS	1	\$	254.00		
4	FRONT BUMPER GRILLE LOWER CENTRE	1	\$	151.00		
5	FRONT BUMPER CLOSING ELEMENTS UPPER CENTRE	1	\$	271.00	\$	173.60
6	FRONT BUMPER SUPPORT ELEMENT UPPER	1	\$	66.00		
7	RADIATOR GRILLE	1	\$	1,205.00	\$	964.00
8	FRONT BUMPER AIR GUIDE GRILLE LH / RH	2	\$	5,600.00		
9	FRONT WHEEL SPOILER FRONT LH / RH	2	\$	114.00		
10	FRONT REINFORCEMENT BEAM	1	\$	5,000.00	\$	787.60
11	FRONT BUMPER FOAM FILLER	1	\$	139.00	\$	110.80
12	FRONT BUMPER SUPPORT	2	\$	29.00		
13	FRONT BUMPER GUIDE SECTION LH / RH	2	\$	82.00		
14	FRONT BUMPER TOP COVER	1	\$	143.00	\$	114.00
15	FRONT BUMPER BRACKET LH	1	\$	255.00		
16	STICKER SIGNAGE " CAUTION HIGH VOLTAGE"	1	\$	16.00	\$	12.40
17	STICKER SIGNAGE " FOR AIR CONDITIONER"	1	\$	34.00	\$	26.96
18	SIGNAL HORN HIGH TONE LH	1	\$	214.00		
19	SPRING SHACKLE HIGH TONE LH	1	\$	28.00		
20	FRONT FENDER LH / RH	2	\$	2,222.00		
SUB TOTAL SPARE PARTS		:	\$	18,819.00	\$	4,369.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	4,369.36
21	FRONT FENDER ATTACHMENTS	1	\$ 60.00		
22	FRONT FENDER BRACE LOWER LH / RH	2	\$ 264.00		
23	FRONT FENDER BRACKET FRONT LH / RH	2	\$ 118.00		
24	POP RIVET	8	\$ 31.00	\$	24.32
25	FRONT WHEEL HOUSING LINERS LH / RH	2	\$ 520.00		
26	STONE CHIP GUARD LH	1	\$ 82.00		
27	ADHESIVE TAPE	1	\$ 59.00		
28	STONE CHIP GUARD RH	1	\$ 5,600.00		
29	ADHESIVE TAPE	1	\$ 59.00		
30	BONNET	1	\$ 5,000.00	\$	2,731.20
31	BONNET PROTECTIVE FILM FRONT	1	\$ 51.00		
32	BONNET ATTACHMENTS PARTS	1	\$ 176.00		
33	BONNET LID HINGE LH / RH	2	\$ 166.00	\$	131.68
34	BONNET CATCH HOOK	1	\$ 155.00		
35	BONNET LID LOCK w MICRO SWITCH	1	\$ 228.00		
36	BONNET LID LOCK CABLE FRONT	1	\$ 55.00		
37	BONNET EDGE PROTECTION FRONT	1	\$ 31.00	\$	24.72
38	BONNET LOCK COVER	1	\$ 26.00		
39	HEADLIGHT MOUNTING LH/ RH	2	\$ 264.00	\$	105.20
40	HEADLIGHT BRACKET LH / RH	2	\$ 236.00	\$	94.00
SUB TOTAL SPARE PARTS		:	\$ 13,181.00	\$	7,480.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6386 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
		<i>c/f</i>		\$	7,480.48	
41	HEADLIGHT DISCHARGE LAMP LH / RH	2	\$	4,984.00	\$ 3,987.20	
42	HEADLIGHT LIFT CYLINDER LH / RH	2	\$	462.00		
43	HEADLIGHT LIFT CYLINDER HOSE ROLLERS	1	\$	204.00		
44	AIRCON CONDENSER	1	\$	816.00	\$ 652.80	
45	AIRCON CONDENSER BRACKET	1	\$	21.00		
46	CHARGE AIR COOLER	1	\$	628.00		
47	RADIATOR	1	\$	1,442.90		
48	RADIATOR LOWER SUPPORT	1	\$	5,600.00		
49	AIR GUIDE LH / RH	2	\$	84.00	\$ 33.28	
50	READY MIX COOLANT 1.0 L	6	\$	5,000.00		
51	INTAKE MANIFOLD FRONT	1	\$	107.00		
52	BELLOWS RESONATOR	1	\$	119.00		
53	COVER FOR PLENUM CHAMBER	1	\$	83.00		
54	WATER DEFLECTOR STRIP RH	1	\$	75.00		
55	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00	
56	SUNDRIES		\$	400.00	\$ 68.64	
TOTAL SPARE PARTS		:	\$	52,085.90	\$ 12,282.40	
TOTAL LABOUR CHARGES		:	\$	13,444.00	\$ 4,842.00	
GRAND TOTAL		:	\$	65,529.90	\$ 17,124.40	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-27/05/22