



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGM 1800 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY.	S/N \$ 360.00	?
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	250 + 250. S/S
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	S/N \$ 1,400.00	x <u>480</u> S/S.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1500
5	TO RESPRAY FRONT BUMPER, BONNET, <u>HINGES</u> , BOTH ^{RH} FRONT FENDER AND RHS UPPER A-PILLAR. _{only.}	\$ 5,000.00	1650 + 160.
6	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$ 384.00	182
TOTAL LABOUR CHARGES		: \$ <u>13,444.00</u>	

Adrian Lj
 S/S.

Add 1 more day for
 the replacement of
 condenser. S/S

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S	S/NETT	
1	FRONT BUMPER <i>Repaired</i>	1	S	2,725.00 ✓	
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	1	S	271.00 ✗	
3	FRONT BUMPER CLOSING ELEMENTS <i>Not in</i>	1	S	254.00 ✗	
4	FRONT BUMPER GRILLE LOWER CENTRE <i>Not in</i>	1	S	151.00 ✗	
5	FRONT BUMPER CLOSING ELEMENTS UPPER CENTRE <i>Not in</i>	1	S	271.00 ✓	<i>S.S.</i>
6	FRONT BUMPER SUPPORT ELEMENT UPPER <i>Not in</i>	1	S	66.00 ✗	
7	RADIATOR GRILLE <i>Crushed</i>	1	S	1,205.00 ✓	
8	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>Not in</i>	2	S	302.00 ✗	
9	FRONT WHEEL SPOILER FRONT LH / RH	2	S	114.00 ✗	
10	FRONT REINFORCEMENT BEAM <i>Dented.</i>	1	S	985.00 ✓	<i>S.S.</i>
11	FRONT BUMPER FOAM FILLER <i>Crushed</i>	1	S	139.00 ✓	
12	FRONT BUMPER SUPPORT ?	2	S	29.00 -	
13	FRONT BUMPER GUIDE SECTION LH / RH <i>Not in</i>	2	S	82.00 ✗	
14	FRONT BUMPER TOP COVER <i>Repaired</i>	1	S	143.00 ✓	
15	FRONT BUMPER BRACKET LH ?	1	S	255.00 ?	
16	STICKER SIGNAGE " CAUTION HIGH VOLTAGE" <i>Not in</i>	1	S	16.00 ✓	
17	STICKER SIGNAGE " FOR AIR CONDITIONER" <i>Not in</i>	1	S	34.00 ✓	
18	SIGNAL HORN HIGH TONE LH ?	1	S	214.00 ?	
19	SPRING SHACKLE HIGH TONE LH ?	1	S	28.00 ?	
20	FRONT FENDER LH / RH <i>RH Dented</i>	2	S	2,222.00 <i>1111</i>	
SUB TOTAL SPARE PARTS			:	\$ 9,506.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENTS	1	S 50.00	+
22	FRONT FENDER BRACE LOWER LH / RH	2	S 264.00	+
23	FRONT FENDER BRACKET FRONT LH / RH	2	S 118.00	+
24	POP RIVET	8	S 31.00	✓
25	FRONT WHEEL HOUSING LINERS LH / RH	2	S 520.00	x
26	STONE CHIP GUARD LH	1	S 82.00	+
27	ADHESIVE TAPE	1	S 59.00	+
28	STONE CHIP GUARD RH	1	S 82.00	+
29	ADHESIVE TAPE	1	S 59.00	+
30	BONNET	1	S 3,414.00	✓
31	BONNET PROTECTIVE FILM FRONT	1	S 51.00	+
32	BONNET ATTACHMENTS PARTS	1	S 175.00	+
33	BONNET LID HINGE LH / RH	2	S 166.00	✓
34	BONNET CATCH HOOK	1	S 155.00	+
35	BONNET LID LOCK w MICRO SWITCH	1	S 228.00	+
36	BONNET LID LOCK CABLE FRONT	1	S 55.00	+
37	BONNET EDGE PROTECTION FRONT	1	S 31.00	✓
38	BONNET LOCK COVER	1	S 26.00	+
39	HEADLIGHT MOUNTING LH / RH	2	S 264.00	+
40	HEADLIGHT BRACKET LH / RH	2	S 236.00	+
SUB TOTAL SPARE PARTS		:	\$ 6,077.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Handwritten notes:
 - Next to 22: } LH RH
 - Next to 25: xhd m
 - Next to 26: xhd m
 - Next to 27: xhd m
 - Next to 28: xhd m
 - Next to 29: xhd m
 - Next to 30: Dented
 - Next to 31: xhd m
 - Next to 32: xhd m
 - Next to 33: Bent
 - Next to 39: LH could
 - Next to 40: LH could
 - Next to 39: 132 } H.S.
 - Next to 40: 118 } H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGM 1800 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT DISCHARGE LAMP LH/RH <i>RH covered</i>	2	\$ 4,984.00	2492 4984. <i>sls.</i>
42	HEADLIGHT LIFT CYLINDER LH / RH <i>2 me m</i>	2	\$ 462.00	+
43	HEADLIGHT LIFT CYLINDER HOSE ROLLERS	1	\$ 204.00	+
44	AIRCON CONDENSER <i>2 FAULT Dented</i>	1	\$ 816.00	<i>sls.</i>
45	AIRCON CONDENSER BRACKET <i>me m</i>	1	\$ 21.00	+
46	CHARGE AIR COOLER <i>me m</i>	1	\$ 628.00	+
47	RADIATOR <i>me m</i>	1	\$ 1,442.90	+
48	RADIATOR LOWER SUPPORT <i>me m</i>	1	\$ 43.00	+
49	AIR GUIDE LH / RH <i>Dented LH</i>	2	\$ 84.00	42 <i>sls</i>
50	READY MIX COOLANT 1.0 L	6	\$ 282.00	+
51	INTAKE MANIFOLD FRONT	1	\$ 107.00	+
52	BELLOWS RESONATOR <i>me m</i>	1	\$ 119.00	+
53	COVER FOR PLENUM CHAMBER	1	\$ 83.00	+
54	WATER DEFLECTOR STRIP RH	1	\$ 75.00	+
55	FRONT NO PLATE <i>dented</i>	S/N	\$ 60.00	+
56	SUNDRIES	5	\$ 400.00	+
TOTAL SPARE PARTS		:	\$ 25,393.90	
TOTAL LABOUR CHARGES		:	\$ 13,444.00	
GRAND TOTAL		:	\$ 38,837.90	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.