

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: JPM 8077
 at Workshop m/s: Enofice
 of _____
 Insured: _____
 Policy No. _____
 Claims No. DM22H000446/JT
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: RMS 4200
 IDAC Accident Rport: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: JPM 8077 Yr Regn: 22/07/13
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha 135LC c.c. 135
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 95495 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PMYK60540DD0123310
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 110-70-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 20/2/22 D.O.I. 24/3/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear, n/s. o/s body.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Drink drive.</u>
<u>29/3/22</u>	<u>v/s 81400 informed lee lee (Red 4791.50, 77%)</u>
<u>29/3/22</u>	<u>@ 10.50a revised to prime tag by email.</u>

Date/Time, File Pass to? : Preli. Report : Final Report
 1) 29/3/22 Date/Time, File Return to?
 2) _____
 Report Format : TP
 Lump Sum / I.B.I. (\$) (400))
 Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)) S + RS, SI
 : Interview (\$)) Photos
 : Tech. Invs (\$)) Others
 : Weekend (\$))
 Survey Fee: _____
 Transportation: _____
 TOTAL _____

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

EA

not Authorized

lll

24/3/22

L/S \$1400

Name : Phang Wei Loon (90557086)

Accident Date : 20-Feb-22

Vehicle No : JPM8077

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

4 days.
Weight. After repair

Qty	Description List Items		Amount S(\$)
2	Front fork tube assy	17	\$ 640.00 X
1	Fork under bracket	17	\$ 185.00 X
1	Handle bar	Self	\$ 88.00 ✓
1	Handle bar ends (1 set)	50 cur	\$ 78.00 ✓
1	Hand grip (1 set)	17	\$ 75.00 ✓
1	Side mirrors (1 set)	80 320	\$ 110.00 ✓
1	Side mirror brackets	17	\$ 80.00 X
1	Brake lever	1/c cur	\$ 32.00 X
1	Fairing assy (1 set)	450 cur/cr	\$ 525.00 ✓
1	Front footrest bracket	Self	\$ 65.00 ✓
2	Front footrest rubbers	35 N/S 7017	\$ 70.00 10c
1	Gear pedal	Self	\$ 58.00 ✓
1	Side stand	17	\$ 85.00 ✓
2	Rear footrests	40 N/S cur	\$ 80.00 10c
2	Rear footrest brackets	Self/cr	\$ 156.00 ✓
1	Rear signal (1 set)	17	\$ 150.00 X
1	Exhaust assy	2	\$ 585.00 X
1	Exhaust protector cap	Self	\$ 75.00 X
1	Exhaust protector - black	N/S	\$ 55.00 ✓
1	Rear wheel rim	300 Self/wheel	\$ 380.00 ✓
1	Rear rim shaft	Self	\$ 60.00 X
1	Rear rim bearing	Page	\$ 52.00 ✓
1	Chain cover	2	\$ 68.00 X
1	Engine cover	17	\$ 225.00 X
1	Rear fender	140 2e	\$ 220.00 ✓
1	Rear swing arm	2	\$ 480.00 X
1	Rear handle bar	148 cur	\$ 198.00 ✓
			\$ 4,875.00
		Less 10%	\$ 487.50
			\$ 4,387.50

L/S \$1400

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Phang Wei Loon (90557086)

Accident Date : 20-Feb-22

Vehicle No : JPM8077

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	Surf / rec	\$ 38.00	30
2	Fork oils	11	\$ 30.00	x
2	Fork oil seals	11	\$ 56.00	x
1	Steering cone (1 set)	11	\$ 90.00	x
1	E.R.P. IU	CU7	\$ 180.00	165
1	Rear box	CU7	\$ 380.00	250
1	Rear box bracket	Surf	\$ 180.00	120
			\$ 954.00	

S/No. Labour

1	To provide towing service (LOD) \$35.00	\$	-
2	To check wiring and reset headlamp focusing	\$ 117	80.00 x
3	To provide labour	\$ 280	420.00
4	To repair body frame	\$ 117	350.00 x
			\$ 850.00

Grand Total

\$ 6,191.50

Singapore Dollars: Six Thousand One Hundred Ninety-One and Cents: Fifty only

1717
2380.3

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 02311

Date: 17/3/22

Particular: _____

Vehicle No: JPM 8077 Model No: LC 131

From: T. POUND To: EROFIA

Time: (Day/Night): _____

Others: _____

CASH \$: 35/-

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.