

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	Ī	Ref:	CS/SMO22002711/Uqy3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	1	Date:	02/06/2022	
			(Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBP 8934U	Veh. Inspected		SJM 1866A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2200984/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		24/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA ACCORD 2.0 (A)	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	CL73304681	Colour		SILVER	
	Odometer	220348 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195/65 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195/65 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195/65 R15	BRIDGESTONE		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/03/2022	Inspection Date	•	25/03/2022	
	Survey held at					
	Repairer					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
			,			