

Date: 23/03/2022
Vehicle No: SNC7650X
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA8MC384809-2021
Reg. Year: 2021

Third Party Insurer: MS FIRST CAPITAL
Third Party Veh No: XD7724T
Date of Accident: 22/03/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Ref/CM	\$663.55
SUB TOTAL				\$663.55
LESS 10%				-\$132.71
PARTS TOTAL				\$530.84

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	Ref	\$60.00
2	COATING FOR AFFECTED AREAS	1	Ref	\$240.00
S/N TOTAL				\$300.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPLACE & READJUST FRONT ACCIDENT AREAS & ETC.

\$300.00 2001

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC.

\$300.00 2201

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

Ref \$100.00 X

LABOUR TOTAL \$700.00

TING AN TOTAL \$1,530.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Branch

Branch (Motor Insurance Claims)

Head office

8 Kung Chong Road Singapore 6343
Tel: (+65) 6472 1313

Branch

8A Serangoon North Ave 5 Singapore 554002

Tel: (+65) 6481 1011 Fax: (+65) 6481 1002

10 Ang Mo Kio Ind. Park 2A 601-06 Singapore 568047

Tel: (+65) 6481 1022 Fax: (+65) 6481 1011



Not taken
Repairing 8 days
2 days

81137-20