



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: LOH CHEE HENG		Ref: CS3/AIG21010754/T1vy3e2-1 Date: 05/04/2022 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLB 1479T	Veh. Inspected	SMZ 3188G
Policy No.	7210114442	Coverage (\$)	0.00
Claim No.	1707188627SG	Excess (\$)	0.00
Assign From	LOH CHEE HENG	Assign Date	24/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ CLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD1179422N279341	Colour	SILVER
Odometer	93557 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	14/10/2021	Inspection Date	19/10/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	