

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES708271

Date : 24/03/2022

Vehicle Num. : SKW 7815T

Make/Model : HONDA VEZEL

Chassis/Eng# :

Accident Date : 23/03/2022

Claim No. :

Reference :

Policy No. :

not Authorized
24/3/22
2/58 6500/
6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER		653.10
2.	2PCS	REAR BUMPER SIDE RETAINER		50.40
3.	2PCS	REAR BUMPER SIDE	25.20	423.60
4.	1PC	REAR BUZZER SENSOR	211.80	95.00
5.	1PC	REAR BUMPER UNDERCOVER		218.70
6.	1PC	ANTENNA ASSY- SMARTKEY		93.00
7.	1PC	TAILGATE		1,197.30
8.	1SET	TAILGATE GLASS MOULDING		128.30
9.	2PCS	TAILGATE LAMP		731.40
10.	1PC	TAILGATE GARNISH	365.70	286.70
11.	1PC	TAILGATE TRIM BOARD		353.60
12.	1PC	TAILGATE LOCK		168.00
13.	1PC	TAILGATE WEATHERSTRIP		155.80
14.	1PC	TAILGATE LOGO		37.00
15.	1PC	TAILGATE VEZEL EMBLEM		39.00
16.	1PC	REAR END PANEL		562.70
17.	1PC	REAR END PANEL GARNISH		96.60
18.	2PCS	REAR FENDER INNER TRIM	360.90	721.80
19.	1PC	REAR COMPARTMENT BOARD		256.70
20.	1PC	REAR COMPARTMENT TRAY		266.70
21.	1PC	REAR COMPARTMENT PANEL		959.60
22.	2PCS	TAILLAMP	586.70	1,173.40

not Authorized
24/3/22
2/58 6500/
6 days

320 x 2 = 640

997.30

468 x 2 = 936

CONTINUE / ...



6194.9

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES708271

Date : 24/03/2022
Vehicle Num. : SKW 7815T
Make/Model : HONDA VEZEL
Chassis/Eng# :
Accident Date : 23/03/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2PCS	REAR FENDER ARCH GARNISH <i>Two</i>	208.50	417.00 ✓
		List TotalS\$:		9,085.40
		20.00% Discount S\$:		1,817.08
				7,268.32
		SPECIAL NETT ITEMS :		
1.	1SET	REAR BUMPER REFLECTOR <i>one</i>		400.00
2.	1SET	REAR BUMPER CLIP <i>net</i>		50.00
3.	1SET	REAR BUMPER UNDERCOVER CLIPS <i>net</i>		50.00
4.	1PC	REAR NUMBER PLATE <i>net</i>		45.00
5.	1SET	TAILGATE BODY SEALANT <i>net</i>		80.00
6.	1SET	TAILGATE GLASS SEALANT <i>net</i>		50.00
7.	1SET	TAILGATE GLASS INNER SEAL <i>net</i>		45.00
8.	1SET	TAILGATE TRIM BOARD CLIPS <i>net</i>		100.00
9.	1SET	REAR FENDER INNER TRIM CLIP <i>net</i>		100.00
10.	1SET	REVERSE SENSOR <i>shorted</i>		200.00
11.	1SET	REVERSE CAMERA <i>net</i>		350.00
12.	1SET	REAR COMPARTMENT RUBBER INSULATOR <i>net</i>		350.00
13.	1SET	TAILLAMP CLIPS <i>net</i>		50.00
14.	1SET	REAR FENDER ARCH GARNISH CLIPS <i>net</i>		50.00
		Special Nett Total S\$:		1,920.00

CONTINUE / ...



AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department
Contact : 6419 3000

Estimate : ES708271

Date : 24/03/2022
Vehicle Num. : SKW 7815T
Make/Model : HONDA VEZEL
Chassis/Eng# :
Accident Date : 23/03/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO CHECK LIGHT AND WIRING
WATERTEST TO CHECK FOR LEAKAGE
ANTI-RUST
TO APPLY BODY SEALANT ON BODY JOINTS
REMOVE/REFIT INNER TRIMS TO FACILITATE REPAIR
TRANSFER TAILGATE GLASS
TRANSFER TAILGATE PARTS

50.00 20
50.00 X
150.00 60
150.00 50
150.00 80
120.00 120
120.00 60

INSTALL REVERSE SENSOR

80.00 50

INSTALL REVERSE CAMERA

150.00 X

TO DIAGNOSE AND REPROGRAM

250.00 X

LABOUR/PANEL BEATING
SPRAY PAINTING

1,200.00 800
1,500.00 950

Labour Total S\$:

3,970.00

E. & O.E.

Total S\$: 13,158.32

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P 6611-30
202
P-5289-04
S.N. 670
L-2190
P149-04
203
6519