



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Syed Sufri Bin Syed Haron Reg No/Reg Date SJX2146E / 25/05/201 Date In/Mileage 23/03/2022/ 0 Chassis No KNAKU811MA5082782 Engine No G4KEAH714826 Make/Model KIA/SORENTO 2.4 A EX PREMIUM EDITIO Colour/Trim IM / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/03/2022/ 12:48	TLK	282 / Kevin Leong	48609			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER, BUMPER LWR, SUPPORT & AFFECTED AREA							1200.00
E PNT98000	PAINT WORK ON FRT BUMPER & BONNET							700.00
E PNT88000	REPLACE REAR BUMPER, END PANEL & AFFECTED AREA							1600.00
	REPAIR ON REAR RH FENDER							
E PNT98000	PAINT WORK ON REAR BUMPER, END PANEL & REAR RH FENDER							1050.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							120.00
M SUNDRY	TO TOP UP AIRCON GAS							80.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST							120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR							120.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA							80.00
M SUNDRY	PERFORM RUST PREVENTION							80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY	TO SUPPLY FRT NUMBER PLATE WITH FRAME							50.00
M SUNDRY	SUNDRIES							50.00
M LAMP ASSY-HEAD,LH				1.00	2121.00	20.00	1696.80	
M LAMP ASSY-REAR COMBINATION,LH				1.00	708.00	20.00	566.40	
M COVER-FR BUMPER UPR				1.00	677.00	20.00	541.60	
M MOULDING-FRONT BUMPER A/INTAKE				1.00	27.00	20.00	21.60	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mr Syed Sufri Bin Syed Haron Reg No/Reg Date SJX2146E / 25/05/201 Date In/Mileage 23/03/2022/ 0 Chassis No KNAKU811MA5082782 Engine No G4KEAH714826 Make/Model KIA/SORENTO 2.4 A EX PREMIUM EDITIO Colour/Trim IM / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	24/03/2022/ 12:48	TLK	282 / Kevin Leong	48609

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER-FR BUMPER,LWR	1.00	735.00	20.00	588.00
M COVER-BLANKING FRT FOG,RH	1.00	27.00	20.00	21.60
M BRACKET-FR BUMPER SIDE SUPT,RH	1.00	26.00	20.00	20.80
M ABSORBER-FRONT BUMPER ENERGY	1.00	106.00	20.00	84.80
M GRILLE ASSY-RADIATOR	1.00	348.00	20.00	278.40
M COVER-RR BUMPER	1.00	643.00	20.00	514.40
M LAMP ASSY-REAR FOG & R/REFL,RH	1.00	107.00	20.00	85.60
M MOULDING ASSY-RR BUMPER SIDE,R	1.00	152.00	20.00	121.60
M BRACKET-RR BPR SIDE REINF,RH	1.00	22.00	20.00	17.60
M WIRING ASSY-BUMPER EXTN	1.00	226.00	20.00	180.80
M ABSORBER-REAR BUMPER ENERGY	1.00	88.00	20.00	70.40
M RAIL ASSY-REAR BUMPER	1.00	290.00	20.00	232.00
M GUARD-REAR WHEEL,RH	1.00	59.00	20.00	47.20
M GARNISH ASSY-QTR SIDE,RH	1.00	92.00	20.00	73.60

Confirm & accepted by

Nett 10,563.20
 7% GST on 10563.20 739.42
Total Payable 11,302.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.